

Work Order Tracking (Tr)

800

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2400155 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 05/08/16 04:19:03 AM

Reported By: MTACRON

Phone:

Reported Date: 05/08/16 04:19:03 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address:

City:

Formatted Address:

State/Province:

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / W. Wilson Date 5/10/16 Page 1 of 1
 (Please Print)

Inspected From RA To JH ML # 2 WO# 2400155

Item	Exception Chain Marker No.		Track No.	Rail	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To		N/S		Comp.	Defect			
1.	230 +75		2	S	3-A	S03	D08	Y	N	
2.	229 +80		2		1-A	S05	D01	Y	N	
3.	229 +00		2	W	1-A	S02	D05	R	N	
4.	228 +80		2		5-B	S02	D05	R	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	wheel burns on closure rail
2	flag post battered needs welding
3	stock rail chipped and pitted needs welding
4	stock rail chipped and pitted needs welding

W. Chandler
Trackwalkers Signature

[Signature]
Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2400340 (1RA-OM) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN_MARK >> Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 05/06/16 04:20:59 AM

Reported By: MTACRON

Phone:

Reported Date: 05/06/16 04:20:58 AM

On Behalf Of:

Conslst: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #: >>

Type: >>

Status:

Asset Condition:

Address Information

Service Address: >>

City:

Formatted Address:

State/Province:

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / Williams Date 5/11/16 Page 1 of 1
 (Please Print)

Inspected From RA To OM ML # 1 WO# 2400340

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	341 + 00	344 + 36	1	N/S	38/18	R01	D26	Y	N	
2.	389 + 05	391 + 40	1		18/38	R01	D26	R	N	
3.	432 + 00	440 + 30	1		3mm	R01	D26	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

COMMENTS

Item	COMMENTS
1	out of surface and spikes killed ties
2	out of surface and spikes killed ties and out of line
3	out of surface

Chandler
Trackwalkers Signature


Supervisory Certification

Work Order Tracking (Tr)

Roll

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2400191

(20M-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 05/06/16 04:19:25 AM

Reported By: MTACRON

Phone:

Reported Date: 05/06/16 04:19:24 AM

On Behalf Of:

Conslst:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address:

Formatted Address:

City:

State/Province:

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler Williams Date 5/12/16 Page 1 of 1
 (Please Print)

Inspected From OM To RA ML 2 WO # 2400191

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	645	+80	2	N		R01	D05	R	N	
2.	642	+60	2	N		R01	D05	R	N	
3.	640	+50	2	N		R01	D05	R	N	
4.	639	+20	2	N		R01	D05	R	N	
5.	638	+50	2	N		R01	D05	R	N	
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

COMMENTS

Item	COMMENTS
1	running rail chipped and pitted needs welding
2	running rail chipped and pitted needs welding
3	running rail chipped and pitted needs welding
4	running rail chipped and pitted needs welding
5	running rail chipped and pitted needs welding

Chandler Williams
 Trackwalkers Signature


 Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2400203

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 05/06/16 04:19:38 AM

Reported By: MTACRON

Phone:

Reported Date: 05/06/16 04:19:37 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address:

Formatted Address:

City:

State/Province:

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name John Chandler Jefferson Date 5/13/16 Page 1 of 1
 (Please Print)

Inspected From JH To RA ML # 1 WO# **2400203**

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	053 wt	059412	1			R01	D05		Y	
2.	013+58		1			T04	D03		Y	
3.	184	1857	1			C04	D21		Y	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	Rail Pot hole
2	Two block tie broken
3	Cover board missing

John Chandler
 Trackwalkers Signature

[Signature]
 Supervisory Certification