

Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2417223

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO



Classification Description: MTA - METRO

Asset:



Alias:

Location: CHAIN\_MARK



Metro Chain Markers



Work Location:



Work Type: PM



Status: WSCH

Status Date: 05/20/16 04:16:24 AM

Reported By: MTACRON



Phone:

Reported Date: 05/20/16 04:16:23 AM



On Behalf Of:



Consist:



Asset Details

Year:

Manufacturer:



Model:



Serial #:

Type:



Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore



City: BALTIMOR

Formatted Address:

State/Province: MD



Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2417215

(20M-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 05/20/16 04:16:13 AM

Reported By: MTACRON

Phone:

Reported Date: 05/20/16 04:16:13 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

# WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / NATE  
(Please Print)

Date 5/24/16

Page 1 of 1

Inspected From OM To RA ML 2 WO # 2417215

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	645 + 80		2	N		R01	D05	R	N	
2.	642 + 00		2	N		R01	D05	R	N	
3.	640 + 50		2	N		R01	D05	R	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

### COMMENTS

Item	Comments
1	Running rail chipped and pitted needs welding
2	Running rail chipped and pitted needs welding
3	Running rail chipped and pitted needs welding

*Chandler*  
Trackwalkers Signature

*[Signature]*  
Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2417250

(1RA-OM) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN\_MARK > Metro Chain Markers

Work Location: >

Work Type: PM

Status: WSCH

Status Date: 05/20/16 04:16:37 AM

Reported By: MTACRON

Phone:

Reported Date: 05/20/16 04:16:37 AM

On Behalf Of:

Consist: >

Asset Details

Year:

Manufacturer: >>

Model: >

Serial #:

Type: >

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

# WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name J. George Date 5/27/16 Page 1 of 1  
 (Please Print)

Inspected From RA To OM ML # 1 **WO#** 2417280

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	638+45		2			Rol	DOS	R	N	
2.	640+50		2			Rol	DOS	R	N	
3.	639+25		2			Rol	DOS	R	N	
4.	642		2			Rol	DOS	R	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

### COMMENTS

Item	COMMENTS
1	Reversing rail chipped needs welding
2	Chipped + pitted rail needs welding
3	Chipped + pitted reversing rail needs welding
4	Reversing rail chipped + pitted need welding

J. George Nest H  
**Trackwalkers Signature**

[Signature]  
**Supervisory Certification**

Work Order Tracking (Tr)

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2414633

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

\* Work Type: PM

Status: WSCH

Status Date: 05/18/16 04:16:07 AM

Reported By: MTACRON

Phone:

Reported Date: 05/18/16 04:16:08 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD



# VEHICLE TRACK INSPECTION REPORTING FORM

Name D. Byrd / N. Gale Date 5-27-16 Page 1 of 1  
 (Please Print)

Inspected From OM To JH ML # 2 WO # 2414633

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	69.8	69.4	2	S		C03	MISSING	5	N	
2.	47.8	47.2	2	N		M06	Lightly	5	N	
3.	46.	46	2	S		C03	MISSING	5	N	
4.	38	38	2	N		C03	MISSING	5	N	
5.	34.2	34.2	2	N		C03	MISSING	5	N	
6.	22.2	22.2	2	N		M06	Lightly	5	N	
7.	18.4	18.4	2	N		C03	MISSING	5	N	
8.	05.6	05.6	2	N		C03	MISSING	5	N	
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
	All coverboards are missing or damaged (need to be replaced) lights are out in different locations from the Portal to John Hopkins

  
 Trackwalkers Signature

  
 Supervisory Certification



Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2414633      VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO     

Classification Description: MTA - METRO

Asset:     

Alias:

Location: CHAIN\_MARK      Metro Chain Markers

Work Location:     

Work Type: PM     

Status: WSCH

Status Date: 05/18/16 04:16:07 AM

Reported By: MTACRON     

Phone:

Reported Date: 05/18/16 04:16:06 AM

On Behalf Of:     

Consist:     

Asset Details

Year:

Manufacturer:     

Model:     

Serial #:

Type:     

Status:

Asset Condition:

Address Information

Service Address: 1206      6301 Wabash Ave Relisterstown Plaza Baltimore           City: BALTIMOF

Formatted Address:      State/Province: MD



Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2417204

(2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN\_MARK >> Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 05/20/16 04:16:07 AM

Reported By: MTACRON >>

Phone:

Reported Date: 05/20/16 04:16:07 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD

# WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Jafferson / Chandler Date 5/28/14 Page 1 of 1  
 (Please Print)

Inspected From RA To JH ML # 2 WO# 2417204

Item	Exception Chain Marker No.		Track No.	Rail	Switch No.	Codes		Status	Repair	W. O.
	From	To		N/S		Comp.	Defect	S/Y/R	Y/N	#
1.	232+00	227+20	2	W/S		R01	D26	Y	N	
2.	230+90		2	S		J02	D05	R	N	
3.	230+90		2	S	3-A	S02	D08	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	out of sub base ties punched and mud condition
2	standard joint chipped and potted needs welding
3	wheel bars on stock rail

Christie Chandler  
 Trackwalkers Signature

[Signature]  
 Supervisory Certification