

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2425407

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION WA

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

\* Work Type: PM

Status: WSCH

Status Date: 05/27/16 04:17:26 AM

Reported By: MTACRON

Phone:

Reported Date: 05/27/16 04:17:25 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD

# WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / Satterfield Date 6/1/16 Page 1 of 1  
 (Please Print)

Inspected From JH To RA ML # 1 WO# 2425407

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	228 ±00	232 ±00	1	N/S	1B-36	R01	D26	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	out of sumpack and ties pumping

Timothy Chandler  
 Trackwalkers Signature

[Signature]  
 Supervisory Certification

4 hrs  
Friday OT

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2425399

(20M-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN\_MARK >> Metro Chain Markers

Work Location: >>

# Work Type: PM

Status: WSCH

Status Date: 05/27/16 04:17:16 AM

Reported By: MTACRON >>

Phone:

Reported Date: 05/27/16 04:17:15 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #: >>

Type: >>

Status: >>

Asset Condition: >>

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

# WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler Date 6/2/16 Page 1 of 1  
 (Please Print)

Inspected From OM To RA ML 2 WO # **2425399**

item	Exception Chain Marker No.		Track No.	Rail	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To		N/S		Comp.	Defect			
1.	645 + 80		2	N		RO1	D05	R	N	
2.	642 + 00		2	N		RO1	D05	R	N	
3.	640 + 50		2	N		RO1	D05	R	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	running rail chipped and pitted needs welding
2	running rail chipped and pitted needs welding
3	running rail chipped and pitted needs welding

Chandler  
 Trackwalkers Signature

[Signature]  
 Supervisory Certification

### Quick Reporting (Tr)

Query Find Work Order Select Action



#### List View Quick Reporting Specifications

Work Order: 2043307 2 RAJH Rail Side Worn (S) (27-32 Deg) 056E-064E

Classification: CHAIN\_MARKER CHAIN\_MARKER

Asset: 1340630 TRACK METRO EAST 2

Alias: TME2

Classification: CHAIN\_MARKER

Class Description: CHAIN\_MARKER

Warr

Location: METROMOW Maintenance of Ways

Work Location: 056E Chain Markers East, Charles Center Interlock, 056E

Work Group: MTA472

Consist:

#### Work Details

Component: MOW-R01 RUNNING RAIL

Total Planned Cost: 0.00

Position: SOUTH South

Total Actual Cost: 0.00

Reason for Repair: WD01 Preventive Maintenance Inspection

Repair Limit Amount:

Work Accomplished:

Reported By: MALCHIN

Part Failure:

Reported Date: 08/12/15 03:09:32 PM

Parent WO:

Telematics Code:

Telematics Transaction:

GL Account: J05-####-04

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

- List
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2422536

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

\* Work Type: PM

Status: WSCH

Status Date: 05/25/16 04:15:19 AM

Reported By: MTACRON

Phone:

Reported Date: 05/25/16 04:15:18 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

# VEHICLE TRACK INSPECTION REPORTING FORM

Name N. Gale, R. Ringrose Date June 3, 2016 Page 1 of 1  
 (Please Print)

Inspected From OM To JH ML # 2 WO # **2422536**

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	620	600	2				D14			
2.	492+80		2				D14			
3.	Sudbrook	Tunnel	2				M06			
4.	JH	Portal	2				M06			
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	Low ballast
2	Low ballast
3	Lights not working
4	Lights not working

  
 Trackwalkers Signature

  
 Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2422536

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 05/25/16 04:15:19 AM

Reported By: MTACRON

Phone:

Reported Date: 05/25/16 04:15:18 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Relisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD



# VEHICLE TRACK INSPECTION REPORTING FORM

Name Sutterfield / Byrd Date 6-3-16 Page 1 of 1  
 (Please Print)

Inspected From OM To JH ML # 1 WO # 2422536

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	69	69	1	S		C03	DAMAGED	S	N	
2.	59.6	59.6	1	S		C03	MISSING	S	N	
3.	57.6	57.6	1	S		C03	MISSING	S	N	
4.	55.2	55.2	1	S		C03	MISSING	S	N	
5.	50.8	50.8	1	S		C03	MISSING	S	N	
6.	47.4	47.4	1	S		C03	MISSING	S	N	
7.	42.	42.8	1	S		N26	OUT OF SERVICE	S	N	
8.	34.4	34.4	1	S		C03	MISSING	S	N	
9.	34.2	34.2				C03	MISSING	S	N	
10.	28.6	28.6	1	S		C03	MISSING	S	N	
11.	18.6	18.4	1	S		C03	MISSING	S		
12.	16.2	16.2	1	S		C03	MISSING	S	N	
13.	13.8	13.8	1	S		C03	MISSING	S	N	
14.	11.4	11.4	1	S		M06	CRACKED	S	N	
15.	03.6	03.6	1	S		C03	MISSING	S	N	
16.										
17.										
18.										
19.										
20.										

Item COMMENTS

All Covenboard are missing on Admap. (need to be replaced) Lighter out in different location from Nordst do John Hopkewitz

*David Byrd*  
Trackwalkers Signature

*[Signature]*  
Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2426416 (1RA-OM) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 05/27/16 04:17:30 AM

Reported By: MTACRON

Phone:

Reported Date: 05/27/16 04:17:30 AM

On Behalf Of:

Constat:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

# WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / Sattlerfield Date 6/3/16 Page 1 of 1  
 (Please Print)

Inspected From RA To OM ML # 1 WO# 2428416

Item	Exception Chain Marker No.		Track No.	Rail	Switch	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To		N/S	No.	Comp.	Defect			
1.	341+00	344+30	1	N/S	3B-1B	RO1	D26	Y	N	
2.	389+05	391+40	1	N/S	1B-3B	RO1	D26	R	N	
3.	432+00	440+30	1	N/S	3MM	RO1	D26	Y	N	
4.	452+00	456+00	1		3B	RO1	D14	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	out of surface and spikes killed ties
2	out of surface and out of line and spikes killed ties
3	out of surface
4	low ballast

Chandler  
Trackwalkers Signature

[Signature]  
Supervisory Certification