

Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2435617

(2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO



Classification Description: MTA - METRO

Asset: >>



Alias:

Location: CHAIN_MARK >> Metro Chain Markers



Work Location: >>



Work Type: PM

Status: WSCH

Status Date: 06/03/16 04:16:27 AM

Reported By: MTACRON



Phone:

Reported Date: 06/03/16 04:16:26 AM



On Behalf Of: >>



Consist: >>



Asset Details

Year:

Manufacturer: >>



Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore



City: BALTIMOR

Formatted Address:

State/Province: MD

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / Williams Date 6/6/16 Page 1 of 1
 (Please Print)

Inspected From RA To JH ML # 2 WO# 2435617

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	232 + 00	227 + 20	2	N/S		R01	D26	Y	N	
2.	230 + 90		2	S		J02	D05	R	N	
3.	230 + 90		2	S	3-4	S02	D08	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	out of surface ties pumping and mud condition
2	standard joint chipped and pitted NEEDS welding
3	wheel gauge on stock rail

Chandler / Williams
 Trackwalkers Signature

[Signature]
 Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2435629

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN_MARK >> Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 06/03/16 04:16:39 AM

Reported By: MTACRON >>

Phone:

Reported Date: 06/03/16 04:16:39 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / Williams / Syad Date 6/9/16 Page 1 of 1
 (Please Print)

Inspected From JH To RA ML # 1 WO# 2435629

Item	Exception Chain Marker No.		Track No.	Rail	Switch	Codes		Status	Repair	W. O.
	From	To		N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	228 + 00	232 + 00	1	N/S	1B/3B	R01	D26	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	out of socket and ties pumping

cd/ams
 Trackwalkers Signature

[Signature]
 Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2435621

(20M-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 06/03/16 04:16:29 AM

Reported By: MTACRON

Phone:

Reported Date: 06/03/16 04:16:28 AM

On Behalf Of:

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name A. JEFFERSON Date 6-10-16 Page 1 of 1
 (Please Print)

Vehicle Riding

Inspected From OM To RA ML 2 WO # **2435612**

Item	Exception Chain Marker No.		Track No.	Rail	Switch	Codes		Status	Repair	W. O. #
	From	To		N/S	No.	Comp.	Defect	S/Y/R	Y/N	
1.	528+00	530+75	1	M/S	1-B 3-B	R01	D2L	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

COMMENTS

Item	COMMENTS
1	<i>OUT OF SURFACE AND OUT OF LINE</i>

A. Jefferson

 Trackwalkers Signature

[Signature]

 Supervisory Certification

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2435838 (1RA-OM) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 06/03/16 04:16:43 AM

Reported By: MTACRON

Phone:

Reported Date: 06/03/16 04:16:43 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1208

6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD

WEEKLY TRACK WALKING INSPECTION REPORTING FORM

Name Chandler / Jefferson Date 6/10/16 Page 1 of 1
 (Please Print)

Inspected From RA To OM ML # 1 **WOM** **2435638**

Item	Exception Chain Marker No.		Track No.	Rail	Switch	Codes		Status	Repair	W. O.
	From	To		N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	341 +00	344 +30	1	N/S	SB/I-B	R01	D26	Y	N	
2.	375 +80		1		LB	S05	D05	Y	N	
3.	389 +10	391 +40	1	N/S		R01	D26	R	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

COMMENTS

Item	COMMENTS
1	out of surface and spike killed ties
2	frog point and wing area chipped
3	out of surface and out of line and spike killed ties

Justin Chandler
Trackwalkers Signature

[Signature]
Supervisory Certification

Work Order Tracking (Tr)

BOM

Find Work Order



Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2432497

VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN_MARK >> Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 06/01/16 04:35:12 AM

Reported By: MTACRON >>

Phone:

Reported Date: 06/01/16 04:35:12 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Relisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD

VEHICLE TRACK INSPECTION REPORTING FORM

Name U Gale, D Byrd Date 06-11-16 Page 1 of 1
 (Please Print)

Inspected From OM To JH ML # 2 WO # 2432497

Item	Exception Chain Marker No.		Track No.	Rail N/S	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	694	686	2				D14			
2.	514	510	2				D14			
3.	Portal	JH	2				M06			
4.	442	452	2				D26			
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
1	Low ballast
2	Low ballast
3	Lights need to be repaired in tunnel
4	out of surface bumpy ride through Millford Mill Curve



 Trackwalkers Signature



 Supervisory Certification