

Work Order Tracking (Tr)

Query Find Work Order Select Action

- List View
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records

Work Order: 3266174 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO Site: MET

Classification Description: MTA - METRO Failure Class:

Asset: Problem Code:

Alias: Priority:

Location: CHAIN_MARK Metro Chain Markers Asset/Location Priority:

Work Location: Is Task?

Work Type: PM Parent WO:

Status: APPR Warranty Situation Present: N

Status Date: 01/28/18 01:33:48 PM Maintenance Alert?

Reported By: MTACRON Repair Order?

Phone: Has Follow-up Work?

Reported Date: 01/26/18 04:17:56 AM Quick PM?

On Behalf Of:

Consist:

Asset Details

Costs

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Total Planned Cost: 0.00

Total Actual Cost: 0.00

Repair Limit Amount:

Current Asset Value:

GL Account: J05-####-047

Accepts Charges?

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 1/31/18 Inspection Area: 2 RAJH Walking Riding Parent WO # 3266174

Item	Exception Chain Marker Number		Track No.	Position	Switch No.	Exception Codes		Priority 1-5	Alias
	From	To				Component	Defect		
1	067	90W	2	Both		R08	003	3	TMW2
2									
3									
4									
5									
6									
7									


EXCEPTION REMARKS

Use Priority Coding: 1 2 3 4 5

1	Both J"s battered and pumping								Child WO #	2877835
									Child WO #	
									Child WO #	
									Child WO #	
									Child WO #	
									Child WO #	
									Child WO #	

Inspection Completed? Yes No If No, Why? _____

Track Inspector (Print) Michael Alchin

Track Inspector (Signature) 

Track Inspector (Print) Richard Nelson

Track Inspector (Signature) 

Watchman (Print) Armedie Red. Sa
 Supervisor (Signature) 

Watchman (Signature) 

Right Of Way Track Section Inspectors Report

2RA-JH - Workgroup: MTA472

START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	ALIAS	COMPONENT	QTY	DEFECT	PRI CODE	POSITION	REPORT DATE	WORK ORDER
0	0	0	0	TMW2CC3A	LEAD OR CLOSURE RAIL	0	CHIPPED / PITTED	2	LEFT	7/21/15	2013908
9	0	14	0	TME2	TUNNEL DRAIN	0	TRASH AND DEBRIS	2	BOTH	9/7/16	2571333
14	25	0	0	TME2	RUNNING RAIL	0	CHIPPED / PITTED	3	NORTH	1/15/16	2253600
28	0	31	0	TME2	RUNNING RAIL	0	SHELLED	2	NORTH	7/29/17	3018182
34	0	32	0	TMW2	TUNNEL STRUCTURE	0	LEAKING	2	SOUTH	12/17/15	2218384
34	0	0	0	TMW2	TUNNEL LEAK	0	LEAKING	2	BOTH	8/16/16	2541446
34	0	34	0	TMW2	CLIP	8	BROKEN/SHEARED	2	SOUTH	4/8/17	2861523
46	0	0	0	TMW2	TUNNEL SHAFT	1	DAMAGED HARDWARE	2	SOUTH	9/28/16	2597312
46	40	0	0	TME2	RAIL	0	CORRUGATED		NORTH	6/15/17	2958710
46	0	50	0	TME2	CLIP	0	BROKEN/SHEARED	3	BOTH	7/29/17	3018184
46	40	0	0	TMW2	RUNNING RAIL	0	CORRODED	2	NORTH	10/13/17	3127426
46	0	50	0	TME2	TUNNEL INVERT (TRACKBED)	0	TRASH AND DEBRIS	3	BOTH	11/29/17	3186993
49	85	50	10	TME2	TUNNEL INVERT (TRACKBED)	0	BLOCKAGE	3	BOTH	11/29/17	3187001
55	60	0	0	TME2	LORD	0	LATERAL MOVEMENT	3	BOTH	9/25/15	2100249
56	50	56	75	TME2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	7/22/15	2015103
59	50	54	0	TME2	RAIL	0	CHIPPED / PITTED		NORTH	6/15/17	2958693
59	50	54	0	TMW2	RUNNING RAIL	0	CHIPPED / PITTED	3	SOUTH	10/13/17	3127421
60	0	60	90	TMW2	TUNNEL DRAIN	0	TRASH AND DEBRIS	2	BOTH	10/13/17	3127422
66	90	0	0	TME2JH1A	SWITCH POINT	0	CHIPPED / PITTED	3	RIGHT	4/14/17	2869377
67	0	68	0	TMW2	CONTINUOUS GROUT PLINTH	0	DETERIORATING	3	BOTH	12/5/15	2202890
67	90	0	0	TMW2	INSULATED JOINT	0	BATTERED		BOTH	4/21/17	2877835
67	70	0	0	TME2JH3A	FROG	0	TOP WEAR (RAIL)	2	SOUTH	4/21/17	2877842
67	0	69	0	TMW2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	6/15/17	2958666
67	0	0	0	TME2JH3A	SWITCH POINT	0	CHIPPED / PITTED	3	LEFT	10/5/17	3115055
67	0	68	10	TME2JH1A	COVERBOARD	100	MISSING	2	THIRD RAIL	10/15/14	3140927
68	50	67	70	TMW2	CROSSTIES 8' 6"	55	PUMPING	4	BOTH	7/21/15	2014043
68	65	0	0	TMEXJH	FROG	0	CRACKED / SPLIT	3	WEST	3/25/17	2841524
68	90	0	0	TMW2BH3A	FROG	0	NEEDS WELDING	2	SOUTH	4/21/17	2877832
69	0	0	0	TMW2BH3A	SAFETY WALK	0	MISSING	2	SOUTH	7/21/15	2013791
69	45	0	0	TMW2	SWITCH TIES	2	DETERIORATING	3	BOTH	4/21/17	2877826
69	25	0	0	TMW2BH3A	HEEL BLOCK BOLTS	1	DAMAGED HARDWARE	3	SOUTH	4/21/17	2877829
70	0	70	5	TME2JH1A	STOCK RAIL	25	SIDE WEAR (RAIL)	3	RIGHT	8/12/15	2043020
79	10	0	0	TMW2	COVERBOARD	0	ARCING	3	THIRD RAIL	8/26/15	2060168

No Change Comment 3

Sw Pt Side

Right Of Way Track Section Inspectors Report

2RA-JH - Workgroup: MTA472

START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	ALIAS	COMPONENT	QTY	DEFECT	PRI CODE	POSITION	REPORT DATE	WORK ORDER
194	20	0	0	TMW2	TUNNEL STRUCTURE	0	SAFETY HAZARD	3	SOUTH	9/16/15	2088344
208	50	0	0	TMW2	COVERBOARD	0	POOR SUPPORT	2	NORTH	7/21/15	2013861
214	0	202	0	TMW2	RUNNING RAIL	1200	CHIPPED / PITTED	3	NORTH	11/15/17	3170741
214	0	202	0	TMW2	RUNNING RAIL	0	CHIPPED / PITTED	3	NORTH	11/21/17	3178162
220	0	226	0	TMW2	RUNNING RAIL	30	WORN BEYOND TOLERANCE	3	NORTH	9/7/16	2571765
221	45	0	0	TMW2	END APPROACH	0	ARCING	3	THIRD RAIL	8/28/15	2062903
221	80	0	0	TMW2	RUNNING RAIL	0	ENGINE BURN FRACTURE (EBF)		BOTH	10/18/16	2626213
224	20	224	10	TMW2	CONTINUOUS GROUT PLINTH	0	CRACKED / SPLIT	3	BOTH	8/12/15	2043032
229	85	0	0	TMW2	CROSSTIE EXTENDER/DOG BONE	1	MISSING	2	00	5/23/17	2924067
243	0	240	0	TMW2	RUNNING RAIL	28	WORN BEYOND TOLERANCE	3	NORTH	7/22/15	2014946
257	0	248	0	TMW2	RUNNING RAIL	31	WORN BEYOND TOLERANCE	4	NORTH	7/20/17	3006647
264	0	261	0	TMW2	RUNNING RAIL	27	SIDE WEAR (RAIL)	3	SOUTH	8/11/15	2041956
270	0	266	0	TMW2	RIGHT OF WAY	0	TRASH AND DEBRIS	2	BOTH	9/7/16	2571760
272	10	0	0	TMW2	SAFETY WALK	0	MISSING	2	NORTH	7/21/15	2013781
272	10	0	0	TMW2	INSULATED JOINT	2	BATTERED	2	BOTH	7/20/17	3006633
278	90	275	0	TMW2	RUNNING RAIL	27	SIDE WEAR (RAIL)	3	SOUTH	8/12/15	2043011
305	75	0	0	TMW2	COVER BOARD BRACKET	1	BROKEN/SHEARED	3	THIRD RAIL	11/15/17	3170728
307	65	307	50	TMW2	COVERBOARD	15	POOR SUPPORT	2	NORTH	7/21/15	2013863
307	50	307	70	TMW2	COVERBOARD	2	MISSING	3	THIRD RAIL	11/15/17	3170726
332	60	0	0	TMW2	INSULATED JOINT	0	BATTERED	2	SOUTH	7/20/17	3006585