

### Work Order Tracking (Tr)

**BMXAA45911 - Status change**

Query Find Work Order Select Action



List View Work Order Plans Actuals Activities Measurements Axle Configuration Related Records

Work Order: 3208028

Tri-Monthly Yard SWINSP Track 1 OM,OC

[Attachments](#)

Classification: MTA \ METRO

Site: ME1

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 12/16/17 01:12:12 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 12/15/17 04:19:28 AM

Quick PM?

On Behalf Of:

Consist:

#### Asset Details

#### Costs

Year:

Total Planned Cost: 442.08

**MOW TRI-MONTHLY YARD SWITCH INSPECTION TRACK # 1 OM, OC**

Track	Switch I.D.	Location		Inspection Date	The Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Hardware	Standard Joints	Insulated Joints	Welds	Ballast	
		YARD	DATE													
1	167-A	WEST	1/26/2018	2	3	2	3	2	3	2	2	2	2	2	2	1-5
1	171-B	WEST	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2
1	135-A	WEST	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2
1	133-A	WEST	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2
1	131-A	MIDDLE	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2
1	129-A	MIDDLE	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2
1	127-A	EAST	1/26/2018	2	3	2	2	2	3	2	2	2	2	2	2	2
1	125-A	EAST	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2
OM	9A/7B	TAIL	1/26/2018	3	3	2	2	2	2	2	2	2	2	2	2	2
OM	9B	TAIL	1/26/2018	3	3	2	2	2	2	2	2	2	2	2	2	2
OC	9	SIDING	1/26/2018	2	2	2	2	2	2	2	2	2	2	2	2	2

**COMMENTS:**

OM9A/7B LH Switch Point side worn

171B Forg Point side worn

167A LH Curve Switch Point / Closure Rail side worn

Parent WO #

3208028

Use Priority Coding:



Inspection Completed?  Yes  No If No, Why?

Michael Alchin

Track Inspector (Print)

*Richard Nelson*  
 Track Inspector (Signature)

Michael Alchin

*Richard Nelson*  
 Track Inspector (Signature)

Supervisory (Signature)

Date

### Work Order Tracking (Tr)

Query

Find Work Order



Select Action



List View

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Work Order: 3216733

Tri-Monthly Yard SWNSP Track 2,3,4



Attachments



Classification: MTA \ METRO



Site: ME1

Classification Description: MTA - METRO

Failure Class:

Asset:



Problem Code:

Alias:

Priority:

Location: CMWABYARD Chain Marker Wabash Yard



Asset/Location Priority:

Work Location:



Is Task?

Work Type: PM



Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 12/22/17 12:43:52 PM

Maintenance Alert?

Reported By: MTACRON



Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 12/22/17 04:18:51 AM



Quick PM?

On Behalf Of:



Consist:



#### Asset Details



#### Costs

Year:

Total Planned Cost: 442.08

**MOW TRI-MONTHLY YARD SWITCH INSPECTION TRACK # 2,3,4**

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Hardware	Standard Joints	Insulated Joints	Welds	Ballast
	WABASH	YARD	DATE	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5
2	169	WEST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	167-B	WEST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	165	WEST	2/1/18	2	3	3	2	3	2	2	2	2	2	2
2	163	WEST	2/1/18	2	3	2	2	2	2	2	2	2	2	2
2	133-B	WEST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	135-B	WEST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
3	137	WEST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	129-B	MIDDLE	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	131-B	MIDDLE	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	125-B	EAST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
2	127-B	EAST	2/1/18	2	2	2	2	2	2	2	2	2	2	2
3	101	EAST	2/1/18	2	3	3	2	3	2	2	3	3	2	2
3	113	EAST	2/1/18	2	3	3	3	3	2	2	2	2	2	2
3	111	EAST	2/1/18	2	3	3	3	2	2	2	2	2	2	2
4	115	EAST	2/1/18	2	2	2	2	2	2	2	2	2	2	2

COMMENTS:

Parent WO # 3216733 Use Priority Coding: 1 2 3 4 5

Inspection Completed?  Yes  No If No, Why?

Michael Alchin

Track Inspector (Print)

*Michael Alchin*  
 Track Inspector (Signature)

Track Inspector (Signature)

*Michael Alchin*  
 Track Inspector (Signature)

Supervisory (Signature)

Date

### Work Order Tracking (Tr)

Query Find Work Order Select Action

List View Work Order Plans Actuals Activities Measurements Axle Configuration Related Records

Work Order: 3223969

Classification:  Attachments

Classification Description: MTA - METRO Site: METRO

Asset:  Failure Class:

Alias:  Problem Code:

Location: CMWABYARD Chain Marker Wabash Yard Priority:

Work Location:  Asset/Location Priority:

Work Type:  Is Task?

Status: APPR Parent WO:

Status Date: 12/31/17 11:20:11 AM Warranty Situation Present: N

Reported By:  Maintenance Alert?

Phone:  Repair Order?

Reported Date:  Has Follow-up Work?

On Behalf Of:  Quick PM?

Consist:

#### Asset Details

#### Costs

Year:	Total Planned Cost:	442.08
-------	---------------------	--------

**MOW TRI-MONTHLY YARD SWITCH INSPECTION TRACK # 5,6,7,9,11,12**

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Point Rail L/R	Closure S/C	Frog	Stock Rail	Plates	Hardware	Standard Joints	Insulated Joints	Welds	Ballast
Wabash	YARD	DATE	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5	1-5
5	141	WEST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
6	143	WEST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
7	145	WEST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
11	151	WEST	2-6-18	2	2	3	2	3	2	2	2	3	2	2
12	153	WEST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
12	159-A	WEST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
6	119	EAST	2-6-18	2	2	2	2	2	2	2	N/A	2	2	2
6	117	EAST	2-6-18	2	2	2	2	3	2	2	N/A	2	2	2
6	103	EAST	2-6-18	2	2	3	2	3	2	2	2	3	2	2
9	121	EAST	2-6-18	2	2	2	2	2	2	2	N/A	2	2	2
9	105	EAST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
11	123	EAST	2-6-18	2	2	2	2	2	2	2	2	2	2	2
11	107	EAST	2-6-18	2	2	2	2	2	2	2	2	2	2	2

COMMENTS:

Parent WO # 3223969

Use Priority Coding: 1 2 3 4 5

Inspection Completed?  Yes  No If No, Why?

Michael Alchin

Track Inspector (Print) Richard Welton

Track Inspector (Print) *Richard Welton*

Supervisory (Signature)

Track Inspector (Signature) *Richard Welton*

Track Inspector (Signature) *Richard Welton*

Date