

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2806555 AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>> [icon]

Alias:

Location: OLDCOURTF/ >>> Old Court Maintenance Facility [icon]

Work Location: >>> [icon]

Work Type: PM [icon]

Status: WSCH

Status Date: 03/02/17 04:20:44 AM

Reported By: MTACRON >>>

Phone:

Reported Date: 03/02/17 04:20:43 AM [icon]

On Behalf Of: >>>

Consist: >>> [icon]

Asset Details

Year:

Manufacturer: >>> [icon]

Model: [icon]

Serial #:

Type: [icon]

Status:

Asset Condition:

Address Information

Service Address: 1206 >>> 6301 Wabash Ave Reisterstown Plaza Baltimore [icon]

Formatted Address:

Street Address: 6301 Wabash Ave [icon]

Multiple Assets.Locatlons and CIs Filter

0 - 0 of 0

Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2806551 **AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN**

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>>

Alias:

Location: OLDCOURTF/ >>> Old Court Maintenance Facility

Work Location: >>>

Work Type: PM

Status: WSCH

Status Date: 03/02/17 04:20:41 AM

Reported By: MTACRON >>>

Phone:

Reported Date: 03/02/17 04:20:41 AM

On Behalf Of: >>>

Consist: >>>

Asset Details

Year:

Manufacturer: >>>

Model: >>>

Serial #:

Type: >>>

Status:

Asset Condition:

Address Information

Service Address: 1206 >>> 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls Filter

0 - 0 of 0

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	MM-3	439+35	3-24-17	Y	S	Y	Y	Y	S	S	S	Y	S	S
2	MM-1A	439+35	3-24-17	Y	S	S	Y	Y	S	S	Y	Y	S	S
1	RP-3B	389+35	3-24-17	S	S	S	S	S	S	S	S	S	S	S
1	RP-1B	391+05	3-24-17	S	S	S	S	S	S	S	S	S	S	S
2	RP-3A	391+05	3-24-17	S	S	S	S	S	S	S	S	S	S	S
2	RP-1A	389+35	3-24-17	S	S	S	S	S	S	S	S	S	S	S
2	RP-17	376+60	3-24-17	Y	S	S	Y	Y	S	S	S	Y	S	N/A
1	RP-21	376+80	3-24-17	Y	Y	Y	S	Y	S	Y	Y	Y	S	N/A
1	RP-19B	376+60	3-24-17	S	S	Y	Y	Y	S	Y	Y	Y	S	N/A

COMMENTS
 RP 17 - Lags pos. rot + piece worn and IT south rail chipped
 RP 21 - missing hardware frog needs grinding
 RP 19 - frog point chipped rd battered

WORK ORDER # 2806551

Inspectors

C. Chandler
 P. Miles

Date

3/24/17
 3/24/17

Supervisor

