

Work Order Tracking (Tr)

Query

Find Work Order



Select Action



List View

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

1

Work Order: 2893620

AREA #4(BH-JH) MOW MONTHLY MAINLINE SWITCH INS

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority: 1

Location: OLDCOURTF/ Old Court Maintenance Facility

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 05/24/17 10:06:21 AM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 05/02/17 04:17:36 AM

Quick PM?

On Behalf Of:

Consist:

Asset Details

Costs

Year:

Total Planned Cost: 442.08

Manufacturer:

Total Actual Cost: 0.00

MOW MONTHLY MAINLINE SWITCH INSPECTION AREA #4 BH-JH

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	BH-3B	066+45	5/24/17	S	S	S	S	S	S	S	S	S	S	N/A
1	BH-1B	069+30	5/24/17	S	S	S	Y	S	S	S	S	S	S	N/A
2	BH-3A	069+30	5/24/17	Y	S	S	S	S	S	Y	S	S	S	N/A
2	BH-1A	066+45	5/24/17	S	Y	S	Y	S	S	S	S	S	S	N/A
1	CC-3B	004+70	5/24/17	N/A	Y	S	S	S	S	S	S	S	S	N/A
1	CC-1B	007+65	5/24/17	N/A	Y	S	Y	S	S	S	S	S	S	N/A
2	CC-3A	007+65	5/24/17	N/A	S	S	S	S	S	S	Y	Y	S	N/A
2	CC-1A	004+70	5/24/17	N/A	Y	S	S	S	S	S	Y	Y	S	N/A
1	JH-3B	070+05NE	5/24/17	N/A	Y	S	S	S	S	S	S	S	S	N/A
1	JH-1B	067+00NE	5/24/17	N/A	Y	S	S	S	S	S	S	S	S	N/A
2	JH-3A	067+00	5/24/17	N/A	Y	S	S	S	S	S	S	S	S	N/A
2	JH-1A	070+06	5/24/17	N/A	Y	S	S	S	S	S	S	S	S	N/A

COMMENTS: Ties in intire interlocking are pumping on both tracks.

BH-3A = Machine timbers deteriorating under switch machine.

WORK ORDER # **2851812**

Inspectors  Date 5-24-17 Supervisor 

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #4 BH-JH

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	BH-3B	066+45	5-24-17	S	S	S	S	S	S	S	S	S	S	N/A
1	BH-1B	069+30	5-24-17	S	S	S	Y	S	S	S	S	S	S	N/A
2	BH-3A	069+30	5-24-17	Y	S	S	S	S	S	Y	S	S	S	N/A
2	BH-1A	066+45	5-24-17	S	Y	S	Y	S	S	S	S	S	S	N/A
1	CC-3B	004+70	5-24-17	N/A	Y	S	S	S	S	S	S	S	S	N/A
1	CC-1B	007+65	5-24-17	N/A	Y	S	Y	S	S	S	S	S	S	N/A
2	CC-3A	007+65	5-24-17	N/A	S	S	S	S	S	S	Y	S	S	N/A
2	CC-1A	004+70	5-24-17	N/A	Y	S	S	S	S	S	S	Y	S	N/A
1	JH-3B	070+05NE	5-24-17	N/A	Y	S	S	S	S	S	S	S	S	N/A
1	JH-1B	067+00NE	5-24-17	N/A	Y	S	S	S	S	S	S	S	S	N/A
2	JH-3A	067+00	5-24-17	N/A	Y	S	S	S	S	S	S	S	S	N/A
2	JH-1A	070+06	5-24-17	N/A	Y	S	S	S	S	S	S	S	S	N/A

COMMENTS: Ties in wire interlocking are pumping on both tracks
 BH-3B - Machine Timbers deteriorating under switch machine.

WORK ORDER # 2851812

Inspectors Robert Nelson Date 5-24-17 Supervisor _____



Work Order Tracking (Tr)

BMXAA4591I - Status

Query Find Work Order Select Action

List View Work Order Plans Actuals Activities Measurements Axle Configuration Related Records

Work Order: 2893624 **AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH INS** Attachments

Classification: MTA \ METRO Site: MET

Classification Description: MTA - METRO Failure Class:

Asset: Problem Code:

Alias: Priority:

Location: OLDCOURTF/ Old Court Maintenance Facility Asset/Location Priority:

Work Location: Is Task?

Work Type: PM Parent WO:

Status: APPR Warranty Situation Present: N

Status Date: 05/07/17 07:18:22 AM Maintenance Alert?

Reported By: MTACRON Repair Order?

Phone: Has Follow-up Work?

Reported Date: 05/02/17 04:17:38 AM Quick PM?

On Behalf Of:

Consist:

Asset Details

Costs

Year:	Total Planned Cost:	442.08
Manufacturer:	Total Actual Cost:	0.00

Due 6/1/17

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	5-31-17	Y	Y	S	S	S	S	S	S	S	S	S
2	OM-7A	704+10	5-31-17	Y	Y	S	S	S	S	S	S	S	S	S
2	OM-3A	688+30	5-31-17	S	Y	S	Y	S	S	S	Y	S	S	S
2	OM-1A	682+36	5-31-17	S	Y	S	Y	S	S	S	S	S	S	S
1	OM-1B	682+36	5-31-17	S	Y	S	Y	S	S	S	S	S	S	S
1	OM-3B	688+30	5-31-17	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	5-31-17	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-1B	525+75	5-31-17	Y	Y	S	Y	Y	S	Y	S	S	S	S
1	OC-3B	632+26	5-31-17	Y	Y	S	Y	Y	S	Y	S	S	S	S
2	OC-3A	632+26	5-31-17	S	Y	S	Y	S	S	S	S	S	S	S
2	OC-1A	525+75	5-31-17	Y	Y	Y	Y	Y	S	S	Y	S	S	Y

COMMENTS OM-3A Battered point worn riser OM-3A Switch point Side work OM-3A miss
 Match standard joint DM-1A side worn switch point OM-1A battered below frog and worn point
 Add riser DM-1T side worn switch point OM-3B frog point battered + worn riser OC-5A frog
 heel battered worn riser OC-1B Tie deterioration + spike kill + wheel burns on switch
 points and closure rail OC-3B Tie deterioration - spike kill - wheel burns on switch points
 battered joint at heel block + frog top worn OC-1A Heel block joint battered tie height - standing
 worn chipped riser - Tie deteriorating OC-3B Low ballast

WORK ORDER # 2893624

Inspectors

Michael Allen

Date 5-31-17

Supervisor

[Signature]

Joe Brockway for Budgen

Work Order Tracking (Tr)

BMXAA4591I - Status change(s)

Find Work Order



Find Navigation Item

List View Work Order Plans Actuals Activities Measurements Axle Config

Go To Applications

My Recent Applications

Administration

Analytics

Assets

Available Queries

All Records

All Bookmarks

LTRAIL MOW PM

Semi Annual Switch Inspection

Team Time Dev P

Common Actions

New Work Order

Clear Changes

Change Status

More Actions

Workflow

SLAs

Plans

Create

View

Work Order: 2851812

AREA #4(BH-JH) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: APPR

Status Date: 05/09/17 04:26:40 PM

Reported By: MTACRON

Phone:

Reported Date: 04/01/17 04:37:40 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Due By 5/1/17

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2851808

AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/16/17 08:24:06 AM

Reported By: MTACRON

Phone:

Reported Date: 04/01/17 04:37:38 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls



0 - 0 of 0

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #3 RA-PO

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM	CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	RA-3B	351+25	5/6/17	S	S	S	S	S	S	S	S	S	S	S
1	RA-1B	344+15	5/6/17	S	S	S	S	S	S	S	S	S	S	S
1	RA-5A	348+55	5/6/17	S	S	S	S	S	S	S	S	S	S	S
1	RA-7B	349+10	5/6/17	S	S	S	S	S	S	S	S	S	S	Y
2	RA-9A	348+10	5/6/17	S	S	S	Y	S	S	S	S	S	S	S
2	RA-3A	344+15	5/6/17	S	S	S	S	S	S	Y	S	S	S	S
2	RA-1A	341+25	5/6/17	S	S	S	S	S	S	S	S	S	S	S
1	PO-3B	229+10	5/6/17	S	S	S	S	S	S	S	S	S	S	S
1	PO-1B	230+80	5/6/17	S	S	S	S	S	S	S	S	S	S	S
2	PO-7B	332+46	5/6/17	S	S	S	S	S	S	S	S	S	S	S
2	PO-3A	230+80	5/6/17	S	S	S	S	S	S	S	S	S	S	S
2	PO-1A	229+10	5/6/17	S	S	S	S	S	S	S	S	S	S	S
2	PO-5B	227+40	5/6/17	S	S	S	S	S	S	S	S	S	S	S

COMMENTS:

8 = Frog point and riser battered Switch RA-9A

6&7 = Low Ballast in Switch RA-5A and RA-7B

9 = Three pandrol clips and blocks missing due to hold down bolts broken on pandrol blocks in frog area.

WORK ORDER # **2851808**

Inspectors

M. Alchin, R. Nelson

Date

5/6/2017

Supervisor



Work Order Tracking (Tr)

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2851804

AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN:

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/16/17 08:22:16 AM

Reported By: MTACRON

Phone:

Reported Date: 04/01/17 04:37:35 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0

Due 5/1/17

MOW MONTHLY MANLINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
1	MM-3	439+35	5-9-17	R	S	S	Y	S	S	S	S	S	S	S
2	MM-1A	439+35		R	S	S	Y	S	S	S	S	S	S	S
1	RP-3B	389+35		S	S	S	S	S	S	S	S	S	S	S
1	RP-1B	391+05		S	S	S	S	S	S	S	S	S	S	S
2	RP-3A	391+05		S	S	S	S	S	S	S	S	S	S	S
2	RP-1A	389+35		S	S	S	S	S	S	S	S	S	S	S
2	RP-17	376+60		N/A	S	S	Y	S	S	Y	Y	S	S	N/A
1	RP-21	376+80		N/A	Y	S	S	Y	S	S	Y	S	S	N/A
1	RP-19B	376+60		N/A	S	S	R	R	S	Y	Y	S	S	N/A

COMMENTS

WORK ORDER # 2851804

Inspectors

Joe Brooking Sr. for Signature

Date

5-9-17

Supervisor

Archie Dis...

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2851800

AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/16/17 08:20:35 AM

Reported By: MTACRON

Phone:

Reported Date: 04/01/17 04:37:33 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls

Filter

0 - 0 of 0

Due By 5/1/17

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	5/10/17	Y	Y	Y	S	Y	S	S	S	S	S	S
2	OM-7A	704+10	5/10/17	Y	Y	Y	Y	Y	S	S	S	S	S	S
2	OM-3A	688+30	5/10/17	S	Y	S	Y	S	S	S	Y	S	S	S
2	OM-1A	682+36	5/10/17	S	Y	S	Y	S	S	S	S	S	S	S
1	OM-1B	682+36	5/10/17	S	Y	S	Y	S	S	S	S	S	S	S
1	OM-3B	688+30	5/10/17	S	S	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	5/10/17	S	S	S	S	S	S	S	S	S	S	S
1	OC-1B	525+75	5/10/17	Y	Y	Y	S	S	S	S	S	S	S	S
1	OC-3B	632+26	5/10/17	Y	S	S	S	S	S	S	S	S	S	S
2	OC-3A	632+26	5/10/17	Y	S	S	S	S	S	S	S	S	S	S
2	OC-1A	525+75	5/10/17	Y	S	Y	Y	Y	S	S	Y	S	S	S

COMMENTS Tie Condition = Deteriorating

Switch Points = Side worn. Closure Rails = Side Worn.

Frogs = Top Worn & Battered.

Stock Rails = Wheel burns, Side worn, battered.

Standard Joints = Rail ends are battered.

WORK ORDER # 2851800

Inspectors

Michael R. ...

Date

5/10/17

Supervisor

Arredy Redin