

### Work Order Tracking (Tr)

Find Work Order 
Select Action

- List View
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2982781 AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN:

Attachments

Classification: MTA \ METRO >>

Site: METRO

Classification Description: MTA - METRO

Failure Class:  >>

Asset:  >>

Problem Code:

Alias:

Priority:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Asset/Location Priority:

Work Location:  >>

Is Task?

Work Type: PM

Parent WO:  >>

Status: APPR

Warranty Situation Present: N

Status Date: 07/20/17 10:10:10 AM

Maintenance Alert?

Reported By: MTACRON >>

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 07/02/17 04:17:11 AM

Quick PM?

On Behalf Of:  >>

Consist:  >>

#### Asset Details

#### Costs

Year:  >>

Manufacturer:  >>

Total Planned Cost: 442.08

Total Actual Cost: 0.00

# MOW MONTHLY MANLINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
1	OM-5A	704+10	7-20-17	S	Y	S	S	S	S	S	S	S	S	S
2	OM-7A	704+10	7-20-17	Y	Y	S	S	S	S	Y	S	S	S	S
2	OM-3A	688+30	7-20-17	S	Y	S	Y	S	S	S	S	S	S	S
2	OM-1A	682+36	7-26-17	S	S	S	Y	S	Y	S	S	S	S	S
1	OM-1B	682+36	7-20-17	S	Y	S	Y	S	S	S	S	S	S	S
1	OM-3B	688+30	7-20-17	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	7-20-17	S	S	S	Y	S	S	S	S	S	S	S
1	OC-1B	525+75	7-20-17	Y	Y	S	Y	Y	S	Y	S	S	S	S
1	OC-3B	632+26	7-20-17	Y	Y	Y	Y	Y	S	Y	S	S	S	S
2	OC-3A	632+26	7-20-17	S	S	S	Y	S	S	S	S	S	S	S
2	OC-1A	525+75	7-20-17	Y	S	S	Y	Y	S	S	S	S	S	S

**COMMENTS** OC-5A - frog riser worn OC-1B - Stock rail wheel burns frog riser chipped  
 legs timber bed OC-1B ties bed switch point wheel burns frog point  
 and riser worn OC-3B Pattern ties spike hole switch point side wbrn + burned  
 closure rail side worn frog riser + point top worn OC-3B - frog riser  
 worn DM-5A - curve switch point side wbrn - DM-1A. Deteriorating ties. Curve switch point  
 side worn - loose lass DM-5B side wear point frog point buttend + riser worn DM-3B - frog  
**WORK ORDER #** 2982981 / point buttend riser worn + switch point worn - DM-1A - frog point buttend  
 frog worn DM-1B - frog riser worn - switch point side worn

Inspectors Fabian J Brady Date \_\_\_\_\_ Supervisor Arno & Kelly  
Joe Overbury