

Light Rail MOW

Daily Track Inspection

Name Rollard Date 1-27-18 Page 2 of 2

Watchman Lam WO# 3261210

Inspection From Linthicum To Cromwell

BWT

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.					373-3	S306	349	Y	N	
5.	376+95					S305	322	Y	N	
6.	376+95					S305	305	Y	N	
7.	377+00					J301	347	Y	N	
8.	371+50					M315	311	Y	N	
9.										
10.										
11.										
12.										

Items	Comments
4	No. 2 rod rubbing against tie
5	2 Loose bolts in west frog of diamond
6	Rail in the frog area is battered, chipped and pitted
7	Several arcing spots in rail end at joint.
8	Hill erosion causing 25' area around track to be fouled. 7 cribs are fouled.
	Track inspection complete

Were switches in area inspected? YES C NO \_\_\_\_\_

Is this a Special Inspection? YES \_\_\_\_\_ NO C

Reason for Inspection \_\_\_\_\_

[Signature]  
Track Inspectors Signature

[Signature]  
Supervisory Certification

1/29/18  
Date