

C

Light Rail MOW

Daily Track Inspection

Name Pollard Lam Date 1-20-2014 Page 2 of 2

Watchman Schisher WO# 3251311

Inspection From BWT To _____

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ms

Comments

no new defects noted

inspection complete

Were switches in area inspected? YES NO

Is this a Special Inspection? YES NO

Reason for Inspection _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

1/22/14
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331886

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Manufacturer:		Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:	Mileage Meter:			

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-####-###-#####-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION		LTRAIL_DESCRIPTION			
		TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD			

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331886 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

WO	Description	Class	Status	Relationship
3251311	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Pollard Lam Date 1-20-2018 Page 1 of 2

Watchman Schishor WO# 3251311

Inspection From Linthicum To Cromwell
S 355700 S 484700

Items	Exception Chain Marker No.		Track No.	Rail	Switch	Codes		Status	Repair	W.O
	From	To		E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ms Comments

No new defects

INSPECTION COMPLETE

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

1/22/18
Date

C

Light Rail MOW

Daily Track Inspection

Name Pollard Lam Date 1-20-2014 Page 2 of 2

Watchman Schisher WO# 3251311

Inspection From BWT To _____

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ms _____ Comments no new defects noted

Inspection Complete

Were switches in area inspected? YES NO

Is this a Special Inspection? YES NO

Reason for Inspection _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

1/22/14
Date



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

Crew ID: DAY-B

WO # 3251311

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Alias:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Manufacturer:	Type:
Serial Number:	License:	
Service Address:	1155 344 West North Ave, Baltimore MD	

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
Cl:				

Sched Start:	
Sched Finish:	
Target Start:	1/24/18
Target Finish:	1/24/18
Actual Start:	1/20/18
Actual Finish:	1/20/18
Report Date:	1/16/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48481

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
---------------	-----------	-------------	-----------	---------------	-----------------

LTRAIL_DESCRIPTION		LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		
--------------------	--	--------------------	-------------------------------------------------------------	--	--

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3251311 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Log	Date	Class	Created By	Subject	Description	Long Description
	1/20/18	WORKORDER	MPOLLARD		track inspection	no new defects noted in area
						Inspection complete



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 3251311 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Actual Labor												
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
20	AREPAIR	MPOLLAF					10	N		08:00	00:00	210.32
20	AREPAIR	GLAM					10	N		08:00	00:00	210.32
20	AREPAIR	TSCHISLI					10	N		08:00	00:00	210.32
Total Actual Labor:											630.96	



MD - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3251311 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

C

Light Rail MOW

Daily Track Inspection

Name Pollard Lam Date 1-20-2014 Page 2 of 2

Watchman Schisher WO# 3251311

Inspection From BWI To _____

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ms _____

Comments

NO NEW DEFECTS NOTED

INSPECTION COMPLETE

Were switches in area inspected? YES NO

Is this a Special Inspection? YES NO

Reason for Inspection _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

1/22/14
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3245054 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
riding inspection no new defects noted

Alias:	Location:	CHAIN_MARKER:LT Rail Chain Markers	Status:
Asset:	Manufacturer:		Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

Cl: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	1/14/18
Target Finish:	1/14/18
Actual Start:	1/22/18
Actual Finish:	1/22/18
Report Date:	1/11/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-#####-#####
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
---------------	-----------	-------------	-----------	---------------	-----------------

LTRAIL_DESCRIPTION		LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		
--------------------	--	--------------------	--------------------------------------------	--	--



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 3245054 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
 riding inspection no new defects noted

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		ARABETT			N					08:00	00:00	217.36
Total Actual Labor:											217.36		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3245054 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
riding inspection no new defects noted

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor