

Annual Backflow Assembly Test Report



A P Fire Protection

www.apfireprotection.com
 7612 N 71st Ave, Glendale, AZ 85303
 Phone: (623) 772-5344 Fax: (623) 772-5384

Location Address

20245 North 67th Ave
 Glendale, AZ 85308

C-16 ROC 251919 CR-67 ROC 251920

Water Purveyor City of Glendale	Schedule I.D. 272586
Owner Contact	Owner Phone Number
Location Contact Steven	Location Contact Number 904-477-4559
Monitoring Company	Phone # / Password

Location Names / Address		Owner Name / Address	
Name KinderCare 301462	Name Century Fire Protection		
Address 20245 N 67th Ave	Address 2450 Satellite Blvd		
City, State, Zip Glendale, AZ 85308	City, State, Zip Duluth, GA 30093		

Manufacturer	Model Number	Size	Serial Number
Watts	009M1QT	2"	224050
Water Meter Number	Union	Shut-Off #1	Shut-Off #2
94968930	No	I.B.V. Threaded	I.B.V. Threaded

Location of Assembly	NWC of Building At N ENT
Shut-Off Location	At Meter

New Install	Replacement Assembly	Containment	Domestic Yes	Fireline
		Isolation	Irrigation	Locked

Valve Type	Double Check Assembly		Relief Valve		PVB / SVB	
	Check #1	Check #2	Relief Valve	Back Pressure	SVB	PVB
Initial Test	Held At 8.9	Held At	Opened At 2.1			
	Closed Tight Yes	Closed Tight Yes	Did Not Open	Air Inlet		
	Leaked	Leaked	Notes	Opened At		
	Shut off #1	Shut off #2		Did Not Open		

Repair Info	Check #1		Check #2		Relief Valve		PVB / SVB	
	Cleaned		Cleaned		Cleaned		Check Held At	
	New Rubber Kit		New Rubber Kit		New Rubber Kit		Leaked	
	Leaked		Leaked		Leaked		Cleaned	
							Rubber Kit	

Final Test	Check #1		Check #2		Relief Valve		PVB / SVB	
	Closed Tight		Closed Tight		Opened At		Air Inlet	
	Held At		Held At				Check Held	

Initial Test	Date	1/1/2023	Tester #	03-2102108	Test Kit #	09172099
	Tester Signature			Print Name		Status
				Cody Buckmaster		Pass

Repair	Date		Tester #		Test Kit #	
	Repaired By Signature			Print Name		

Final Test	Date		Tester #		Test Kit #	
	Tester Signature			Print Name		Status

Comments Letter Code: 221012ABQ

Annual Backflow Assembly Test Report



A P Fire Protection

www.apfireprotection.com
 7612 N 71st Ave, Glendale, AZ 85303
 Phone: (623) 772-5344 Fax: (623) 772-5384

Location Address

20245 North 67th Ave
 Glendale, AZ 85308

C-16 ROC 251919 CR-67 ROC 251920

Water Purveyor City of Glendale	Schedule I.D. 272587
Owner Contact	Owner Phone Number
Location Contact Steven	Location Contact Number 904-477-4559
Monitoring Company	Phone # / Password

Location Names / Address		Owner Name / Address	
Name KinderCare 301462	Name Century Fire Protection		
Address 20245 N 67th Ave	Address 2450 Satellite Blvd		
City, State, Zip Glendale, AZ 85308	City, State, Zip Duluth, GA 30093		

Manufacturer	Model Number	Size	Serial Number
Febco	825Y	1.5"	BF1454
Water Meter Number	Union	Shut-Off #1	Shut-Off #2
66631514	Yes	I.B.V. Threaded	I.B.V. Threaded

Location of Assembly NWC of Building At N Entrance

Shut-Off Location At Meter

New Install	Replacement Assembly	Containment	Domestic Yes	Fireline
		Isolation	Irrigation	Locked

Valve Type	Double Check Assembly		Relief Valve		PVB / SVB	
	Check #1	Check #2	Relief Valve	Back Pressure	SVB	PVB
Initial Test	Held At 5.4	Held At	Opened At 2.2			
	Closed Tight Yes	Closed Tight Yes	Did Not Open	Air Inlet		
	Leaked	Leaked	Notes	Opened At		
	Shut off #1	Shut off #2		Did Not Open		

Repair Info	Double Check Assembly		Relief Valve		PVB / SVB	
	Cleaned	New Rubber Kit	Cleaned	New Rubber Kit	Check Held At	Leaked
					Cleaned	
					Rubber Kit	

Final Test	Check #1	Check #2	Relief Valve	Air Inlet
	Closed Tight	Closed Tight	Opened At	Check Held
Held At	Held At			

Initial Test	Date 1/3/2023	Tester # 03-2102108	Test Kit # 09172099
	Tester Signature		Print Name Cody Buckmaster
			Status

Repair	Date	Tester #	Test Kit #
	Repaired By Signature		Print Name

Final Test	Date	Tester #	Test Kit #
	Tester Signature		Print Name
			Status

Comments Letter Code: 221012ABQ

Annual Backflow Assembly Test Report



A P Fire Protection

www.apfireprotection.com
7612 N 71st Ave, Glendale, AZ 85303
Phone: (623) 772-5344 Fax: (623) 772-5384

Location Address

20245 North 67th Ave
Glendale, AZ 85308

C-16 ROC 251919 CR-67 ROC 251920

Water Purveyor City of Glendale	Schedule I.D. 272588
Owner Contact	Owner Phone Number
Location Contact Steven	Location Contact Number 904-477-4559
Monitoring Company	Phone # / Password

Location Names / Address		Owner Name / Address	
Name KinderCare 301462	Name Century Fire Protection		
Address 20245 N 67th Ave	Address 2450 Satellite Blvd		
City, State, Zip Glendale, AZ 85308	City, State, Zip Duluth, GA 30093		

Manufacturer	Model Number	Size	Serial Number
Febco	825Y	1.5"	H09415
Water Meter Number	Union	Shut-Off #1	Shut-Off #2
66631514	No	I.B.V. Threaded	I.B.V. Threaded

Location of Assembly NWC of Building At N Entrance

Shut-Off Location At Meter

New Install	Replacement Assembly	Containment	Domestic Yes	Fireline
		Isolation	Irrigation	Locked

Valve Type	Double Check Assembly				Reduce Pressure Assembly		PVB / SVB	
Initial Test	Check #1		Check #2		Relief Valve		Back Pressure	
	Held At	7.8	Held At		Opened At	2.2	SVB	
	Closed Tight	Yes	Closed Tight	Yes	Did Not Open		Air Inlet	
	Leaked		Leaked		Notes		Opened At	
	Shut off #1		Shut off #2				Did Not Open	

Repair Info	Double Check Assembly				Reduce Pressure Assembly		PVB / SVB	
Cleaned		Cleaned		Cleaned		Check Held At		
New Rubber Kit		New Rubber Kit		New Rubber Kit		Leaked		
Leaked		Leaked		Leaked		Cleaned		
						Rubber Kit		

Final Test	Check #1		Check #2		Relief Valve		PVB / SVB	
Closed Tight		Closed Tight		Opened At		Air Inlet		
Held At		Held At				Check Held		

Initial Test	Date	1/1/2023	Tester #	03-2102108	Test Kit #	09172099
	Tester Signature			Print Name		Status
				Cody Buckmaster		Pass

Repair	Date		Tester #		Test Kit #	
	Repaired By Signature			Print Name		

Final Test	Date		Tester #		Test Kit #	
	Tester Signature			Print Name		Status

Comments Letter Code: 221012ABQ

Annual Backflow Assembly Test Report



A P Fire Protection

www.apfireprotection.com
7612 N 71st Ave, Glendale, AZ 85303
Phone: (623) 772-5344 Fax: (623) 772-5384

Location Address

20245 North 67th Ave
Glendale, AZ 85308

C-16 ROC 251919 CR-67 ROC 251920

Water Purveyor City of Glendale	Schedule I.D. 272585
Owner Contact	Owner Phone Number
Location Contact Steven	Location Contact Number 904-477-4559
Monitoring Company	Phone # / Password

Location Names / Address		Owner Name / Address	
Name KinderCare 301462	Name Century Fire Protection		
Address 20245 N 67th Ave	Address 2450 Satellite Blvd		
City, State, Zip Glendale, AZ 85308	City, State, Zip Duluth, GA 30093		

Manufacturer	Model Number	Size	Serial Number
Febco	765	1"	HG25920
Water Meter Number	Union	Shut-Off #1	Shut-Off #2
66631514	Yes	I.B.V. Threaded	I.B.V. Threaded

Location of Assembly NWC of Building At N Entrance	Shut-Off Location At Meter
---	-----------------------------------

New Install	Replacement Assembly	Containment	Domestic	Fireline
		Isolation	Irrigation Yes	Locked

Valve Type	Double Check Assembly		Reduce Pressure Assembly		PVB / SVB
Initial Test	Check #1	Check #2	Relief Valve		Back Pressure
	Held At	Held At	Opened At		SVB
	Closed Tight	Closed Tight	Did Not Open		PVB
	Leaked	Leaked	Notes		Air Inlet
	Shut off #1	Shut off #2			Opened At 2.6

Repair Info	Check #1	Check #2	Relief Valve	PVB / SVB
Cleaned	Cleaned	Cleaned	Cleaned	Check Held At 1.4
New Rubber Kit	New Rubber Kit	New Rubber Kit	New Rubber Kit	Leaked
Leaked	Leaked	Leaked	Leaked	Cleaned
				Rubber Kit

Final Test	Check #1	Check #2	Relief Valve	PVB / SVB
Closed Tight	Closed Tight	Closed Tight	Opened At	Air Inlet
Held At	Held At	Held At		Check Held

Initial Test	Date 1/3/2023	Tester # 03-2102108	Test Kit # 09172099
	Tester Signature		Print Name Cody Buckmaster
			Status Pass

Repair	Date	Tester #	Test Kit #
	Repaired By Signature		Print Name

Final Test	Date	Tester #	Test Kit #
	Tester Signature		Print Name
			Status

Comments The backflow passed, but there is an underground leak on the service side of the line.