



2150 Smithtown Ave., Suite 3, Ronkonkoma, NY 11779
T: 631.580.3191 • F: 631.580.3195 • W: envirohealth.org

November 10, 2016

To: Lindenhurst Union Free School District

Attached please find the results and remediation response of sampling performed in compliance with the United States Environmental Protection Agency's "3T's for Reducing Lead in Drinking Water in Schools", October, 2006 and New York State Department of Health Subpart 67-4 of Title 10, September 2016.

Sincerely,

A handwritten signature in black ink, appearing to read "Glenn Neuschwender", is written over a light gray rectangular background.

Glenn Neuschwender
President

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

ALBANY AVENUE ELEMENTARY SCHOOL	
First Draw Samples Collected	90
First Draw Samples > 15 Parts Per Billion	19
Number of Sources Capped or Taken Off Line	4
Post Remediation Samples <= 15 PPB	12
Number of Sources Pending For Remediation	3
<i>Maximum Pb Concentration Observed</i>	<i>1972</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Prep	SK	1.2	-	-	None	-	-
Kitchen Ware Washing	SK	<1.0	-	-	None	-	-
Kitchen Bathroom	SK	6.2	-	-	None	-	-
Main Office	SK	4.5	-	-	None	-	-
Principal Office Bathroom	SK	11	-	-	None	-	-
Water Fountain Nearby Main Office	WF	<1.0	-	-	None	-	-
Nurse's Office Bathroom	SK	3.4	-	-	None	-	-
Nurse's Office Sink by Desk	SK	4	-	-	None	-	-
Nurse's Office Sink by Closet	SK	10	-	-	None	-	-
Women Bathroom by Room 117	SK	6.5	-	-	None	-	-
Men Bathroom by Room 117	SK	4.5	-	-	None	-	-
Water Fountain by Room 117	WF	4.8	-	-	None	-	-
Faculty Room	SK	4.2	-	-	None	-	-
Room 108	WF	4.9	-	-	None	-	-
Room 106	SK	1.7	-	-	None	-	-
Room 107	SK	<1.0	-	-	None	-	-
Room 105	WF	4.5	-	-	None	-	-
Water Fountain by Room 105	WF	<1.0	-	-	None	-	-
Room 104	WF	3.8	-	-	None	-	-
Room 102	WF	2.9	-	-	None	-	-
Room 202	WF	3.3	-	-	None	-	-
Room 203	WF	124	-	-	-	CAP	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 204	WF	6.2	-	-	None	-	-
Water Fountain by Room 204	WF	6.4	-	-	None	-	-
Boy's Bathroom by Room 204	SK	4.1	-	-	None	-	-
Girl's Bathroom by Room 204	SK	6.7	-	-	None	-	-
Room 208	WF	4.7	-	-	None	-	-
Water Fountain by Room 208	WF	3	-	-	None	-	-
Room 207	WF	5.2	-	-	None	-	-
Room 206	WF	4.8	-	-	None	-	-
Room 209	WF	5.1	-	-	None	-	-
Room 205	WF	5	-	-	None	-	-
Room 210	WF	9.7	-	-	None	-	-
Social Worker Office	SK	8.5	-	-	None	-	-
Girl's Bathroom by Library	SK	6.9	-	-	None	-	-
Boy's Bathroom by Fan Room	SK	<1.0	-	-	None	-	-
Water Fountain nearby Fan Room	WF	1	-	-	None	-	-
Room 216	WF	1.5	-	-	None	-	-
Room 211	WF	1.7	-	-	None	-	-
Water Fountain by Room 211	WF	1.6	-	-	None	-	-
Room 212	WF	3.8	-	-	None	-	-
Room 213	WF	1.5	-	-	None	-	-
Room 214	WF	840	-	-	-	CAP	-
Water Fountain by Room 214	WF	38	9	<1.0	FR	TBD	

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 215	WF	181	-	-	-	CAP	-
Room 116	WF	7.9	-	-	None	-	-
Water Fountain by 64M	WF	1	-	-	None	-	-
Boy's Locker Room	WF	4.6	-	-	None	-	-
Girl's Locker Room	WF	4.2	-	-	None	-	-
Room 114B	WF	4.5	-	-	None	-	-
Water Fountain by Room 113	WF	<1.0	-	-	None	-	-
Room 113	WF	4.5	-	-	None	-	-
Room 112	WF	26	-	-	-	CAP	-
Room 111	WF	5.6	-	-	None	-	-
Room 110	SK	1.2	-	-	None	-	-
Room 109	WF	3.5	-	-	None	-	-
Lavatory by Custodian Office	SK	8.7	-	-	None	-	-
Custodian Office Bath	SK	1.9	-	-	None	-	-
RM 202	SK	58	72	<1.0	FRSLV	Completed FRSLV	16 (10/17/2016) <1.0 (10/26/2016)
RM 203	SK	18	<1.0	<1.0	FR	Completed FR	33 (10/17/2016) <1.0 (10/26/2016)
RM 204	SK	14	-	-	None	-	-
RM 207	SK	7	-	-	None	-	-
RM 206	SK	15	2	<1.0	None	-	-
RM 209	SK	34	<1.0	<1.0	FR	Completed FR	50 (10/17/2016) #2.0 (10/26/2016)
RM 205	SK	2.9	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 210	SK	459	6.7	<1.0	FR	Completed FR	28 (10/17/2016) <1.0 (10/26/2016)
RM 216	SK	7.7	-	-	None	-	-
RM 211	SK	152	3.9	<1.0	FR	Completed FR	20 (10/17/2016) <1.0 (10/26/2016)
RM 215	SK	78	2.3	<1.0	FR	Completed FR	7.2
RM 212	SK	486	5.5	<1.0	FR	Completed FR	26 (10/17/2016) <1.0 (10/26/2016)
RM 213	SK	97	4.9	<1.0	FR	Completed FR	32 (10/17/2016) #1.3 (10/26/2016)
RM 214	SK	1972	12	1.5	FR	Completed FR	112 (10/17/2016)
Custodial Closet SS 2nd Floor	SS	31	1	<1.0	FR	Completed FR	Pending Retest
RM 103	SK	9.7	-	-	None	-	-
RM 104	SK	41	1.6	<1.0	FR	Completed FR	12
RM 105	SK	6.4	-	-	None	-	-
RM 107 BR	SK	12	-	-	None	-	-
RM 106 BR	SK	6.9	-	-	None	-	-
RM 108 BR	SK	4.2	-	-	None	-	-
RM 108	SK	17	<1.0	<1.0	FR	Completed FR	5.5
Custodial Closet SS by RM 117	SS	6.4	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

ALLEGHANY AVENUE ELEMENTARY SCHOOL	
First Draw Samples Collected	65
First Draw Samples > 15 Parts Per Billion	4
Number of Sources Capped or Taken Off Line	1
Post Remediation Samples <= 15 PPB	1
Number of Sources Pending For Remediation	2
<i>Maximum Pb Concentration Observed</i>	<i>974</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Faculty Room	SK	3.1	-	-	None	-	-
Room 2	SK	4.6	-	-	None	-	-
Men's Faculty Bathroom	SK	1	-	-	None	-	-
Hallway by Faculty Room	WF	<1.0	-	-	None	-	-
Women's Faculty Bathroom	SK	1.8	-	-	None	-	-
Nurse's Office	SK	2.3	-	-	None	-	-
Nurse's Office Bathroom	SK	3.7	-	-	None	-	-
Principal Office Bathroom	SK	3.9	-	-	None	-	-
Cafeteria	WF	<1.0	-	-	None	-	-
Kitchen Pot Filler	SK	1.1	-	-	None	-	-
Kitchen Food Prep	SK	1	-	-	None	-	-
Kitchen Bathroom	SK	16	4.9	3.6	FR	SIGN	-
Boys Bathroom by Room 114	SK	1.2	-	-	None	-	-
Hall by Room 114	WF	<1.0	-	-	None	-	-
Girl's Bathroom by Room 114	SK	<1.0	-	-	None	-	-
Room 114 Art	SK	1.7	-	-	None	-	-
Room 111	SK	1.5	-	-	None	-	-
Room 116	SK	1.5	-	-	None	-	-
Room 119	SK	3.6	-	-	None	-	-
Room 118	SK	1.4	-	-	None	-	-
Room 115	SK	2	-	-	None	-	-
Room 120	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 117	SK	2.4	-	-	None	-	-
Room 122	SK	2.9	-	-	None	-	-
Hall by Room 119	WF	<1.0	-	-	None	-	-
Room 119	SK	2.6	-	-	None	-	-
Room 124	SK	2.4	-	-	None	-	-
Room 125 Sink	SK	3.9	-	-	None	-	-
Room 125 Water Fountain	WF	2	-	-	None	-	-
Room 123 Sink	SK	5.1	-	-	None	-	-
Room 123 Water Fountain	WF	1.2	-	-	None	-	-
Hall by Room 121	WF	<1.0	-	-	None	-	-
Room 121	SK	3.1	-	-	None	-	-
Hall by Custodian Delivery	WF	<1.0	-	-	None	-	-
Custodian Delivery Bathroom	SK	1.3	-	-	None	-	-
Hall by Girl's Gym	WF	<1.0	-	-	None	-	-
Ladies bathroom by Gym	SK	3.2	-	-	None	-	-
Men Bathroom by Gym	SK	2.2	-	-	None	-	-
Boys Bathroom by Gym	SK	2.2	-	-	None	-	-
Girls Bathroom by Room 214	SK	3.7	-	-	None	-	-
Room 214	SK	<1.0	-	-	None	-	-
Library Office	SK	3.8	-	-	None	-	-
Room 216	SK	3.2	-	-	None	-	-
Room 213	SK	1.6	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 218	SK	1.4	-	-	None	-	-
Room 220	WF	<1.0	-	-	None	-	-
Room 215	WF	1.3	-	-	None	-	-
Room 222	WF	<1.0	-	-	None	-	-
Room 217	WF	<1.0	-	-	None	-	-
Room 224	WF	<1.0	-	-	None	-	-
Room 215	SK	2.4	-	-	None	-	-
Room 220	SK	974	5.5	7.5	FR	Completed FR	436 Pending Retest
Room 217	SK	1.3	-	-	None	-	-
Room 222	SK	7.6	-	-	None	-	-
Room 224	SK	2	-	-	None	-	-
CC by Room 214	SS	7.5	-	-	None	-	-
Room 117	SK	3.8	-	-	None	-	-
Room 122	SK	6	-	-	None	-	-
Room 119	SK	3.5	-	-	None	-	-
Room 124	SK	7.6	-	-	None	-	-
Room 121 BR	SK	<1.0	-	-	None	-	-
Room 123 BR	SK	42	<2.5	<2.5	FR	Completed FR	2.6
Room 125 BR	SK	6.2	-	-	None	-	-
Room 113	SK	58	3.6	<2.5	FR	Completed FR	847 Pending Retest
CC by Room 114	SS	4.2	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

DANIEL STREET ELEMENTARY SCHOOL	
First Draw Samples Collected	95
First Draw Samples > 15 Parts Per Billion	4
Number of Sources Capped or Taken Off Line	0
Post Remediation Samples <= 15 PPB	1
Number of Sources Pending For Remediation	3
<i>Maximum Pb Concentration Observed</i>	57

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Rm 153	SK	24	<2.5	<2.5	FR	Completed FR	21 (9/20/2016) Pending Flush-Retest
Rm 154	WF	5.5	-	-	None	-	-
Rm 155	WF	1.2	-	-	None	-	-
Rm 156	WF	6	-	-	None	-	-
Rm 157	WF	5.5	-	-	None	-	-
Hallway outside rm 156	WF	<1.0	-	-	None	-	-
Rm 158	WF	2.3	-	-	None	-	-
Rm 159	WF	2.9	-	-	None	-	-
Rm 160	WF	4.4	-	-	None	-	-
Rm 161	WF	2.4	-	-	None	-	-
Rm 162	WF	3	-	-	None	-	-
Girl's BR by rm 162	SK	1.7	-	-	None	-	-
Boy's BR by small gym	SK	<1.0	-	-	None	-	-
Faculty BR (left) by small gym	SK	1.4	-	-	None	-	-
Faculty BR (right) by small gym	SK	3.3	-	-	None	-	-
In between faculty BRs	WF	<1.0	-	-	None	-	-
Library	SK	1	-	-	None	-	-
Boys BR across from library	SK	<1.0	-	-	None	-	-
Girls BR across from library	SK	<1.0	-	-	None	-	-
WF across from rm 143	WF	<1.0	-	-	None	-	-
Rm 143	SK	4	-	-	None	-	-
Rm 126	SK	1	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Rm 145	SK	1.7	-	-	None	-	-
Rm 128	WF	1.5	-	-	None	-	-
Rm 147	SK	5.4	-	-	None	-	-
Rm 130	SK	3.2	-	-	None	-	-
WF outside rm 130	WF	<1.0	-	-	None	-	-
Rm 149	SK	2.8	-	-	None	-	-
Rm 132	SK	<1.0	-	-	None	-	-
Rm 151	SK	1.7	-	-	None	-	-
Rm 134	SK	2.5	-	-	None	-	-
Rm 125	WF	3	-	-	None	-	-
Rm 125 BR	SK	1	-	-	None	-	-
Girls side gym	WF	2.4	-	-	None	-	-
Outside rm 125	WF	<1.0	-	-	None	-	-
Gym teacher BR	SK	<1.0	-	-	None	-	-
Boys side gym	WF	<1.0	-	-	None	-	-
Boys side gym teacher BR	SK	<1.0	-	-	None	-	-
Boys side gym BR	SK	1.1	-	-	None	-	-
Outside girls gym teacher office	WF	1.1	-	-	None	-	-
Custodial office BR	SK	<1.0	-	-	None	-	-
WF outside custodial office	WF	<1.0	-	-	None	-	-
Kitchen prep sk	SK	1.7	-	-	None	-	-
Pot filler	SK	2	-	-	None	-	-
Kitchen BR	SK	3.8	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Café	WF	<1.0	-	-	None	-	-
Principal office BR	SK	2.9	-	-	None	-	-
Nurse Office BR	SK	1.2	-	-	None	-	-
Nurse Office	SK	1.9	-	-	None	-	-
Faculty BR (left) by music room	SK	1.3	-	-	None	-	-
Faculty office by music rm	SK	1.5	-	-	None	-	-
Faculty BR (right) by music room	SK	<1.0	-	-	None	-	-
WF by music rm	WF	1	-	-	None	-	-
Boys BR by main entrance	SK	<1.0	-	-	None	-	-
WF by rm 114	WF	<1.0	-	-	None	-	-
Rm 114	SK	1.2	-	-	None	-	-
Girls BR by main entrance	SK	<1.0	-	-	None	-	-
Rm 116	SK	2.6	-	-	None	-	-
Rm 109	SK	9.8	-	-	None	-	-
Rm 118	SK	3.1	-	-	None	-	-
Rm 111	SK	3	-	-	None	-	-
WF outside rm 120	WF	<1.0	-	-	None	-	-
Rm 120	SK	2.3	-	-	None	-	-
Rm 113	SK	1.9	-	-	None	-	-
Rm 122	SK	1.4	-	-	None	-	-
Rm 122 BR	SK	3.9	-	-	None	-	-
Rm 115	SK	4	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Rm 115 BR	SK	18	35	18	FRSLVPA	Completed FRSLVPA	16 (9/20/2016) Pending Flush-Retest
WF by Rm 124	WF	1.6	-	-	None	-	-
Rm 124	SK	2.2	-	-	None	-	-
Rm 124 BR	SK	1.4	-	-	None	-	-
Rm 117	SK	2.9	-	-	None	-	-
Rm 117 BR	SK	<1.0	-	-	None	-	-
Rm 123	SK	1.7	-	-	None	-	-
Rm 123 BR	SK	1.2	-	-	None	-	-
Rm 123	WF	1.6	-	-	None	-	-
Rm 121	WF	1.6	-	-	None	-	-
Rm 121 BR	SK	<1.0	-	-	None	-	-
Rm 119	WF	1.8	-	-	None	-	-
Rm 119 BR	SK	<1.0	-	-	None	-	-
CC SS by RM 114	SS	<1.0	-	-	None	-	-
RM 119 Rear	SK	13	-	-	None	-	-
RM 121 Rear	SK	4.1	-	-	None	-	-
RM 128 SK (Left)	SK	2	-	-	None	-	-
CC SS by Library	SS	<1.0	-	-	None	-	-
CC SS by RM 162	SS	2.5	-	-	None	-	-
RM 154	SK	57	10	<2.5	FR	Completed FR	39 (9/20/2016) Pending Flush-Retest
RM 155	SK	5.7	-	-	None	-	-
RM 156	SK	30	4.2	<2.5	FR	Completed FR	4.5

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 157	SK	7.3	-	-	None	-	-
RM 158	SK	4.5	-	-	None	-	-
RM 159	SK	5.6	-	-	None	-	-
RM 160	SK	7.1	-	-	None	-	-
RM 161	SK	3.3	-	-	None	-	-
RM 162	SK	2.4	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

EW BOWER ELEMENTARY SCHOOL	
First Draw Samples Collected	55
First Draw Samples > 15 Parts Per Billion	18
Number of Sources Capped or Taken Off Line	18
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	<i>975</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 102	SK	<2.5	-	-	None	-	-
RM 104	SK	<2.5	-	-	None	-	-
RM 106	SK	<2.5	-	-	None	-	-
RM 103	WF	14	-	-	None	-	-
Hallway by RM 102	WF	12	-	-	None	-	-
RM 100	SK	106			FR	CAP	
RM 101	SK	86			FR	CAP	
Hallway by Gym	WF	<2.5	-	-	None	-	-
Boys BR by RM 108	SK	<2.5	-	-	None	-	-
RM 110	SK	<2.5	-	-	None	-	-
Unisex BR by Gym	SK	4.4	-	-	None	-	-
Girls BR by Gym	SK	<2.5	-	-	None	-	-
Kitchen Prep	SK	5.6	-	-	None	-	-
Boys LR	WF	<2.5	-	-	None	-	-
Hallway by RM 109	WF	<2.5	-	-	None	-	-
RM 111	WF	25			FR	CAP	
Hallway by RM 112	WF	4	-	-	None	-	-
RM 113	WF	275			FR	CAP	
RM 114	SK	153			FR	CAP	
Girls BR by RM 213	SK	12	-	-	None	-	-
Hallway by RM 213	WF	15	-	-	None	-	-
RM 213	SK	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Boys BR by RM 211	SK	8.9	-	-	None	-	-
RM 211	SK	19			FR	CAP	
RM 209	SK	11	-	-	None	-	-
RM 207	SK	4.8	-	-	None	-	-
Speech BR	SK	7.8	-	-	None	-	-
Faculty RM	SK	7.6	-	-	None	-	-
Faculty RM BR	SK	3	-	-	None	-	-
Hallway by RM 200	WF	7.6	-	-	None	-	-
RM 202	SK	<2.5	-	-	None	-	-
RM 204	SK	847			FR	CAP	
RM 206	SK	730			FR	CAP	
RM 208	SK	422			FR	CAP	
RM 201	SK	20			FR	CAP	
Girls BR by RM 201	SK	59			FR	CAP	
Boys BR by RM 201	SK	16			FR	CAP	
Fire Panel Room	SK	6.5	-	-	None	-	-
RM 108 BR	SK	16	<1.0	<1.0	FR	SIGN	
Nurses Office	SK	38			FR	CAP	
Principal's Office BR	SK	11	-	-	None	-	-
CC by RM 100	SS	3.2	-	-	None	-	-
RM 100 BR	SK	37			FR	CAP	
RM 102 BR	SK	4.4	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 104 BR	SK	3.8	-	-	None	-	-
RM 106 BR	SK	<1.0	-	-	None	-	-
RM 103	SK	<1.0	-	-	None	-	-
RM 103 BR	SK	5.5	-	-	None	-	-
Girls Locker RM	SK	30			FR	CAP	
Library Office	SK	975			FR	CAP	
CC by RM 208	SS	9.4	-	-	None	-	-
Boys Locker RM	SK	4.2	-	-	None	-	-
CC by Cafeteria	SS	4.3	-	-	None	-	-
RM 111	SK	29			FR	CAP	
RM 113	SK	9.5	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

HARDING AVENUE ELEMENTARY SCHOOL	
First Draw Samples Collected	61
First Draw Samples > 15 Parts Per Billion	3
Number of Sources Capped or Taken Off Line	1
Post Remediation Samples <= 15 PPB	1
Number of Sources Pending For Remediation	1
<i>Maximum Pb Concentration Observed</i>	67

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Custodial Office BR	SK	3.6	-	-	None	-	-
Girls BR SK by Rm 112	SK	<2.5	-	-	None	-	-
Boys BR SK by Rm 112	SK	<2.5	-	-	None	-	-
Women Faculty BR SK by Café	SK	4.3	-	-	None	-	-
WF outside Café	WF	<2.5	-	-	None	-	-
Unisex BR SK by Café	SK	3.6	-	-	None	-	-
Kitchen Prep	SK	3.3	-	-	None	-	-
Kitchen Pot Filler	SK	7.7	-	-	None	-	-
Kitchen BR	SK	11	-	-	None	-	-
Principal's Office BR	SK	4.9	-	-	None	-	-
Nurse Office Main	SK	5	-	-	None	-	-
Nurse Office BR	SK	<2.5	-	-	None	-	-
Nurse Office Back Office	SK	67			FR	CAP	-
Faculty Rm	SK	2.6	-	-	None	-	-
WF Outside Rm 105	WF	3	-	-	None	-	-
Rm 105	WF	<2.5	-	-	None	-	-
Rm 108	WF	3.5	-	-	None	-	-
Rm 108 BR	SK	5.1	-	-	None	-	-
Rm 107	WF	<2.5	-	-	None	-	-
Rm 107 BR	SK	<2.5	-	-	None	-	-
Rm 106	WF	5.6	-	-	None	-	-
Rm 111	SK	5.9	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Rm 114	SK	<2.5	-	-	None	-	-
WF Outside Rm 113 A&B	WF	<2.5	-	-	None	-	-
Rm 113 B	SK	5.5	-	-	None	-	-
Rm 115	SK	6.3	-	-	None	-	-
Rm 118	WF	5.7	-	-	None	-	-
Rm 117	WF	<2.5	-	-	None	-	-
Library Office	SK	9.7	-	-	None	-	-
Rm 119	WF	<2.5	-	-	None	-	-
Men's BR SK by Rm 119A	SK	4	-	-	None	-	-
Women's Faculty BR SK by Gym	SK	4.6	-	-	None	-	-
Men's Faculty BR SK by Gym	SK	3.5	-	-	None	-	-
WF by Rm 120	WF	4.4	-	-	None	-	-
Women's BR SK by Rm 120	SK	5.8	-	-	None	-	-
Room 120	SK	6.9	-	-	None	-	-
Room 121	WF	<2.5	-	-	None	-	-
Room 122	SK	4.7	-	-	None	-	-
Room 123	WF	5.8	-	-	None	-	-
Room 124	SK	6.1	-	-	None	-	-
Room 125	SK	4.9	-	-	None	-	-
Room 126	WF	3.4	-	-	None	-	-
Room 127	WF	6.7	-	-	None	-	-
Room 128	WF	3	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF Outside Rm 128	WF	2.8	-	-	None	-	-
WF Outside of Gym	WF	<2.5	-	-	None	-	-
CC by RM 112	SS	<1.0	-	-	None	-	-
RM 105	SK	5.9	-	-	None	-	-
RM 106	SK	4.2	-	-	None	-	-
RM 107	SK	9.6	-	-	None	-	-
RM 108	SK	47	<1.0	1.3	FR	Completed FR	310 (9/20/2016) Pending Retest
Art RM 112	SK	6.2	-	-	None	-	-
RM 117	SK	2.6	-	-	None	-	-
Comp Lab RM 118	SK	7.2	-	-	None	-	-
Music RM 119	SK	1.9	-	-	None	-	-
CC by RM 121	SS	<1.0	-	-	None	-	-
RM 121	SK	<1.0	-	-	None	-	-
RM 123	SK	18	1.2	<1.0	FR	Completed FR	4.1
RM 126	SK	<1.0	-	-	None	-	-
RM 127	SK	3.9	-	-	None	-	-
RM 128	SK	7.7	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

KELLUM STREET SCHOOL	
First Draw Samples Collected	82
First Draw Samples > 15 Parts Per Billion	8
Number of Sources Capped or Taken Off Line	6
Post Remediation Samples <= 15 PPB	1
Number of Sources Pending For Remediation	1
<i>Maximum Pb Concentration Observed</i>	<i>110</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Custodial Bathroom	SK	<2.5	-	-	None	-	-
Outside Custodial Bathroom	WF	5.1	-	-	None	-	-
Outside Staff Room	WF	13	-	-	None	-	-
Staff Bathroom (Left)	SK	4.7	-	-	None	-	-
Staff Bathroom (Right)	SK	5.4	-	-	None	-	-
Nurse's Office	SK	3.4	-	-	None	-	-
Nurse's Office Bathroom	SK	<2.5	-	-	None	-	-
General Purpose Room	SK	<2.5	-	-	None	-	-
Principal Bathroom	SK	3.8	-	-	None	-	-
Boys Bathroom Near Main Office	SK	<2.5	-	-	None	-	-
Outside Boy's Bathroom	WF	<2.5	-	-	None	-	-
Girls Bathroom Near Main Entrance	SK	<2.5	-	-	None	-	-
Room 109	SK	10	-	-	None	-	-
Room 114	SK	7.6	-	-	None	-	-
Room 116	SK	<2.5	-	-	None	-	-
Room 111	SK	5.2	-	-	None	-	-
Room 118	SK	11	-	-	None	-	-
Room 113	SK	6.1	-	-	None	-	-
Outside Room 118	WF	2.8	-	-	None	-	-
Room 120	SK	3.4	-	-	None	-	-
Room 115	WF	7.1	-	-	None	-	-
Room 122	SK	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Outside RM 117	WF	12	-	-	None	-	-
Room 117	WF	<2.5	-	-	None	-	-
Room 124	SK	3.2	-	-	None	-	-
Room 123	SK	<2.5	-	-	None	-	-
Room 121	SK	<2.5	-	-	None	-	-
Room 119	SK	<2.5	-	-	None	-	-
Hallway Near Gym	WF	4.4	-	-	None	-	-
Custodian Office Bathroom	SK	5.7	-	-	None	-	-
Near Boy's Lacrosse Room	WF	6.2	-	-	None	-	-
Boy's Lacrosse Room Bathroom	SK	5	-	-	None	-	-
Room 112 Bathroom	SK	2.5	-	-	None	-	-
Boy's Bathroom Near Room 141	SK	<2.5	-	-	None	-	-
Room 141	SK	5.4	-	-	None	-	-
Girl's BR Near RM 141	SK	2.6	-	-	None	-	-
Outside RM 126	WF	<2.5	-	-	None	-	-
Room 126	SK	<2.5	-	-	None	-	-
Room 143	SK	2.9	-	-	None	-	-
Room 128	SK	4.1	-	-	None	-	-
Room 145	SK	4.8	-	-	None	-	-
Room 130	SK	<2.5	-	-	None	-	-
Room 147	SK	<2.5	-	-	None	-	-
Outside Room 147	WF	3.1	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 132	SK	4.3	-	-	None	-	-
Room 149	SK	6.5	-	-	None	-	-
Room 134	SK	7.7	-	-	None	-	-
Room 151	SK	4.5	-	-	None	-	-
Quality Assurance Room	SK	11	-	-	None	-	-
Staff BR Across Room 165	SK	5.7	-	-	None	-	-
Between Staff BR's	WF	3.4	-	-	None	-	-
Staff BR Across from RM 165 (Right)	SK	14	-	-	None	-	-
Boys BR Across Room 165	SK	<2.5	-	-	None	-	-
Girls BR Across Room 165	SK	7.8	-	-	None	-	-
Room 162	WF	11	-	-	None	-	-
Room 160	WF	9.6	-	-	None	-	-
Room 158	SK	2.8	-	-	None	-	-
Room 155	SK	7.1	-	-	None	-	-
Room 154	SK	12	-	-	None	-	-
Room 153	SK	40			FR	CAP	-
Prep	SK	37			FR	CAP	-
Kitchen BR	SK	23	<2.5	<2.5	FR	SIGN	
CC by Room 114	SS	4.6	-	-	None	-	-
Room 115	SK	2.9	-	-	None	-	-
Room 115 BR	SK	5	-	-	None	-	-
Room 117	SK	1.4	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 117 BR	SK	5.5	-	-	None	-	-
Room 122 BR	SK	3.1	-	-	None	-	-
Room 124 BR	SK	2.7	-	-	None	-	-
Room 119 BR	SK	1	-	-	None	-	-
Room 121 BR	SK	1.1	-	-	None	-	-
Room 123 BR	SK	1.2	-	-	None	-	-
Kitchen Island	SK	110			FR	CAP	-
Ware Washing Station (L)	SK	11	-	-	None	-	-
Ware Washing Station (R)	SK	8.1	-	-	None	-	-
Boys Coaches Office BR	SK	17	<2.5	<2.5	FR	TBD	
CC by Room 141	SS	2.6	-	-	None	-	-
CC by Room 161	SS	1.3	-	-	None	-	-
Room 161 WF	WF	95			FR	CAP	-
Room 161 SK	SK	94			FR	CAP	-
Room 162	SK	12	-	-	None	-	-
Room 160	SK	27	<2.5	<2.5	FR	Completed FR	13

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

LINDENHURST ADMINISTRATION BUILDING	
First Draw Samples Collected	57
First Draw Samples > 15 Parts Per Billion	9
Number of Sources Capped or Taken Off Line	8
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	1
<i>Maximum Pb Concentration Observed</i>	<i>516</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 210	SK	4.9	-	-	None	-	-
Room 213	WF	2.2	-	-	None	-	-
Room 208	SK	6.2	-	-	None	-	-
Room 211	WF	59			FR	CAP	-
Room 206	SK	4.2	-	-	None	-	-
Room 209	SK	18	<1.0	<1.0	FR		
Women BR by Room 209	SK	5.7	-	-	None	-	-
Men BR by Room 202	SK	2.2	-	-	None	-	-
Room 207	SK	3.9	-	-	None	-	-
Room 202	WF	31			FR	CAP	-
Room 205	WF	315			FR	CAP	-
Conference Room	SK	7.9	-	-	None	-	-
Room 203	SK	5.1	-	-	None	-	-
Room 201	WF	2	-	-	None	-	-
Superintendent Office	SK	3.1	-	-	None	-	-
BR by B&G Office	SK	2	-	-	None	-	-
B&G Office	SK	2.3	-	-	None	-	-
Assistant superintendent BR	SK	6.8	-	-	None	-	-
Room 109	SK	2.4	-	-	None	-	-
Room 111	SK	7	-	-	None	-	-
Room 104	SK	3	-	-	None	-	-
Room 106	SK	4	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 113	WF	68			FR	CAP	-
Room 117	WF	3.9	-	-	None	-	-
Room 108	SK	5.7	-	-	None	-	-
Room 115	WF	6.8	-	-	None	-	-
Room 110	WF	2.8	-	-	None	-	-
Girls BR (Academy)	SK	8.6	-	-	None	-	-
Boys BR (Academy)	SK	6.2	-	-	None	-	-
Kitchen	SK	2.9	-	-	None	-	-
Men's BR by Kitchen	SK	1.6	-	-	None	-	-
Women's BR by Kitchen	SK	1.6	-	-	None	-	-
WF by Girl's Locker Room	WF	3.4	-	-	None	-	-
Girls locker Room BR	SK	7.3	-	-	None	-	-
WF in AP Room	WF	4.7	-	-	None	-	-
Transportation Coordinator Rm	SK	3	-	-	None	-	-
Room 103	SK	5.7	-	-	None	-	-
Board Room	SK	2.8	-	-	None	-	-
WF by Boy's Locker	WF	3.4	-	-	None	-	-
Boys Locker Room BR	SK	3.4	-	-	None	-	-
Custodian BR	SK	8.5	-	-	None	-	-
Room 201	SK	1.7	-	-	None	-	-
Room 205	SK	2.9	-	-	None	-	-
Room 211	SK	2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 213	SK	1.4	-	-	None	-	-
2nd Fl Sink RM	SS	2.5	-	-	None	-	-
Room 202	SK	<1.0	-	-	None	-	-
Assistant Principal BR	SK	29	11	<1.0	FR	SIGN	
Copy Room 113	SK	516	4.7	1.2	FR	SIGN	
Room 117	SK	2.6	-	-	None	-	-
Room 115	SK	62	4.8	1.6	FR	SIGN	
Room 110	SK	15	5.2	2.1	None	-	-
1st Fl Sink RM near Print Shop	SS	1.1	-	-	None	-	-
Room 102 BR	SK	32	1.9	1.3	FR	SIGN	
Transportation RM 101 BR	SK	1.9	-	-	None	-	-
1st Fl Sink RM Near RM 101	SS	1.6	-	-	None	-	-
Room 109 BR	SK	<1.0	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

LINDENHURST GROUND SHOP	
First Draw Samples Collected	5
First Draw Samples > 15 Parts Per Billion	0
Number of Sources Capped or Taken Off Line	0
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	6.8

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Office BR	SK	6.8	-	-	None	-	-
Outside	SP	4.2	-	-	None	-	-
Snack Stand	SK	6.7	-	-	None	-	-
Snack Stand Women's BR	SK	<2.5	-	-	None	-	-
Snack Stand Men's BR	SK	<2.5	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

LINDENHURST HIGH SCHOOL	
First Draw Samples Collected	89
First Draw Samples > 15 Parts Per Billion	3
Number of Sources Capped or Taken Off Line	1
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	2
<i>Maximum Pb Concentration Observed</i>	42

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Custodial Office BR	SK	<1.0	-	-	None	-	-
Sports SP in Custodian Office	SP	5.1	-	-	None	-	-
Snack Room	SK	<1.0	-	-	None	-	-
Café Food Prep	SK	<1.0	-	-	None	-	-
Prep Sink	SK	<1.0	-	-	None	-	-
1st Floor Faculty Dining Area	SK	<1.0	-	-	None	-	-
Boys Coaches Office BR	SK	<1.0	-	-	None	-	-
Boys Locker Room	WF	<1.0	-	-	None	-	-
Boys Locker Room BR	SK	2.3	-	-	None	-	-
Girls Coaches Office BR	SK	<1.0	-	-	None	-	-
Girls Locker Room	WF	<1.0	-	-	None	-	-
Girls Locker Room BR	SK	9.7	-	-	None	-	-
Outside Gym	WF	<1.0	-	-	None	-	-
Girls BR by Café	SK	<1.0	-	-	None	-	-
Boys BR by Café	SK	<1.0	-	-	None	-	-
Nurse Office	SK	1.2	-	-	None	-	-
Nurse Office BR	SK	<1.0	-	-	None	-	-
Weight Room	WF	<1.0	-	-	None	-	-
Main Office Kitchen	SK	<1.0	-	-	None	-	-
Faculty Women BR by Main Entrance	SK	<1.0	-	-	None	-	-
Faculty Men BR by Main Entrance	SK	<1.0	-	-	None	-	-
Womens BR by Band Room	SK	1.4	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Mens BR by Band Room	SK	<1.0	-	-	None	-	-
AP Office	SK	3.9	-	-	None	-	-
Womens BR by Room 155	SK	<1.0	-	-	None	-	-
Mens BR by Room 155	SK	<1.0	-	-	None	-	-
Room 154	SK	<1.0	-	-	None	-	-
Room 153	SK	<1.0	-	-	None	-	-
Outside Room 149	WF	<1.0	-	-	None	-	-
Science Storage RM by RM 150	SK	4.2	-	-	None	-	-
Room 138	SK	5.8	-	-	None	-	-
Room 137	SK	2.1	-	-	None	-	-
Room 155	SK	<1.0	-	-	None	-	-
Room 136	SK	2.1	-	-	None	-	-
Middle Hallway Boys BR	SK	<1.0	-	-	None	-	-
Across Room 136	WF	<1.0	-	-	None	-	-
WF by Room 124	WF	<1.0	-	-	None	-	-
Room 124	SK	<1.0	-	-	None	-	-
Room 109	SK	<1.0	-	-	None	-	-
Room 110	SK	5.5	-	-	None	-	-
Room 120	SK	<1.0	-	-	None	-	-
WF by Room 120	WF	<1.0	-	-	None	-	-
Room 111	SK	<1.0	-	-	None	-	-
Girls BR by Room 112	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF Across Room 121	WF	<1.0	-	-	None	-	-
Room 118	SK	<1.0	-	-	None	-	-
WF by Room 118	WF	<1.0	-	-	None	-	-
Lab 1	WF	2.4	-	-	None	-	-
Lab 2	WF	20			FR	CAP	-
WF by Lab 2	WF	1	-	-	None	-	-
Lab 3	SK	1	-	-	None	-	-
WF Outside Room 130	WF	<1.0	-	-	None	-	-
Room 131	SK	<1.0	-	-	None	-	-
Lab 4	SK	<1.0	-	-	None	-	-
WF by Lab 4	WF	1.8	-	-	None	-	-
Lab 5	SK	1.1	-	-	None	-	-
Lab 6	SK	4.6	-	-	None	-	-
WF by Room 144	WF	<1.0	-	-	None	-	-
Mens BR by Room 212	SK	3.3	-	-	None	-	-
Womens BR by Room 212	SK	<1.0	-	-	None	-	-
WF Outside Room 217	WF	<1.0	-	-	None	-	-
Room 212	SK	3.5	-	-	None	-	-
Room 211	SK	42	5.2	<1.0	FR	TBD	
WF by Room 222	WF	<1.0	-	-	None	-	-
Room 222	SK	<1.0	-	-	None	-	-
Room 223	SK	4.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 224	SK	2.1	-	-	None	-	-
Room Storage	SK	<1.0	-	-	None	-	-
WF Across Room 208	WF	<1.0	-	-	None	-	-
Library	SK	<1.0	-	-	None	-	-
Outside Room 235	WF	<1.0	-	-	None	-	-
Outside Room 231	WF	<1.0	-	-	None	-	-
Womens BR by Room 236	SK	<1.0	-	-	None	-	-
Room 236	SK	3.6	-	-	None	-	-
2nd Floor Faculty Room	SK	<1.0	-	-	None	-	-
Mens BR by Room 255	SK	<1.0	-	-	None	-	-
Room 254	SK	5.8	-	-	None	-	-
Room 237	SK	<1.0	-	-	None	-	-
Room 253	SK	27	5.3	7.1	FR	TBD	
Room 238	SK	3.6	-	-	None	-	-
Room 252	SK	2.6	-	-	None	-	-
Outside Room 249	WF	<1.0	-	-	None	-	-
Outside Room 245	WF	<1.0	-	-	None	-	-
Room 118 SK #1	SK	2.8	-	-	None	-	-
Room 118 SK #2	SK	1.3	-	-	None	-	-
Room 118 SK #3	SK	<1.0	-	-	None	-	-
Room 118 SK #4	SK	<1.0	-	-	None	-	-
Room 118 SK #5	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 118 Office SK #5	SK	3.5	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

LINDENHURST MIDDLE SCHOOL	
First Draw Samples Collected	76
First Draw Samples > 15 Parts Per Billion	10
Number of Sources Capped or Taken Off Line	8
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	2
<i>Maximum Pb Concentration Observed</i>	93

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

WEST GATES AVENUE ELEMENTARY SCHOOL	
First Draw Samples Collected	70
First Draw Samples > 15 Parts Per Billion	5
Number of Sources Capped or Taken Off Line	2
Post Remediation Samples <= 15 PPB	3
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	48

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Prep Sink	SK	1.7	-	-	None	-	-
Kitchen Warewashing	SK	2.8	-	-	None	-	-
Kitchen BR	SK	13	-	-	None	-	-
Room 107	WF	<1.0	-	-	None	-	-
Room 108	WF	11	-	-	None	-	-
Room 109	WF	2.7	-	-	None	-	-
Staff Room	SK	3.8	-	-	None	-	-
Women's BR by Staff RM	SK	2.5	-	-	None	-	-
Classroom by Health Office	WF	2	-	-	None	-	-
Health Office	SK	2.1	-	-	None	-	-
Health Office BR	SK	5	-	-	None	-	-
Room 110	WF	2.7	-	-	None	-	-
Men BR by GPR	SK	1.7	-	-	None	-	-
WF by GPR	WF	3.1	-	-	None	-	-
Women BR by GPR	SK	<1.0	-	-	None	-	-
Boy's BR by Book Room	SK	1	-	-	None	-	-
Girl's BR by RM 113	SK	4.9	-	-	None	-	-
Room 113	WF	3.3	-	-	None	-	-
Room 112	WF	2.8	-	-	None	-	-
Room 115	WF	2.9	-	-	None	-	-
Room 114	SK	2.5	-	-	None	-	-
Room 117	WF	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF by Room 114	WF	<1.0	-	-	None	-	-
Room 116	WF	2.3	-	-	None	-	-
Room 119	WF	3.2	-	-	None	-	-
Room 118	WF	1.7	-	-	None	-	-
Room 120	WF	2.7	-	-	None	-	-
Room 123	SK	14	-	-	None	-	-
Room 122	WF	5.7	-	-	None	-	-
Boy's BR by RM 122A	SK	1.8	-	-	None	-	-
Women BR by Girl's Locker RM	SK	2.3	-	-	None	-	-
Men BR by Boy's Locker RM	SK	2.4	-	-	None	-	-
WF by Room 124	WF	3.2	-	-	None	-	-
Girl's BR by RM 124	SK	1.7	-	-	None	-	-
Room 124	SK	<1.0	-	-	None	-	-
Room 125	WF	1.2	-	-	None	-	-
Room 126	WF	1.2	-	-	None	-	-
Room 127	WF	2.1	-	-	None	-	-
Room 128	WF	1.2	-	-	None	-	-
Room 129	WF	<1.0	-	-	None	-	-
Room 130	WF	2.5	-	-	None	-	-
WF by Room 129	WF	1.3	-	-	None	-	-
Boy's Locker Room	WF	29			FR	CAP	-
Girl's Locker Room	WF	48			FR	CAP	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Principal's Office BR	SK	2	-	-	None	-	-
Custodial Office BR	SK	<1.0	-	-	None	-	-
RM 108	WF	<2.5	-	-	None	-	-
RM 108 BR	SK	<2.5	-	-	None	-	-
RM 107	SK	<2.5	-	-	None	-	-
RM 109	SK	2.9	-	-	None	-	-
RM 112	SK	19	2.6	<2.5	FR	Completed FR	3.7
RM 115	SK	6.2	-	-	None	-	-
RM 113	SK	<2.5	-	-	None	-	-
RM 117	SK	2.5	-	-	None	-	-
RM 116	SK	<2.5	-	-	None	-	-
RM 119	SK	<2.5	-	-	None	-	-
RM 118	SK	21	<2.5	<2.5	FR	Completed FR	4
RM 120	SK	5.4	-	-	None	-	-
Music RM 122	SK	22	2.5	<2.5	FR	Completed FR	3.9
RM 125	SK	6.3	-	-	None	-	-
RM 127	SK	4.9	-	-	None	-	-
RM 126	SK	8.8	-	-	None	-	-
RM 128	SK	5.7	-	-	None	-	-
RM 129	SK	7	-	-	None	-	-
RM 130	SK	8.1	-	-	None	-	-
Janitor Closet by RM 124	SS	3.8	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 110	SK	12	-	-	None	-	-
WF by RM 109	WF	4.1	-	-	None	-	-
Janitor Closet by PTA RM	SS	<2.5	-	-	None	-	-
WF by Gym	WF	14	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
LINDENHURST UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

WILLIAM RALL ELEMENTARY SCHOOL	
First Draw Samples Collected	89
First Draw Samples > 15 Parts Per Billion	13
Number of Sources Capped or Taken Off Line	5
Post Remediation Samples <= 15 PPB	8
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	<i>579</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Food Prep	SK	3.3	-	-	None	-	-
Wash SK	SK	4.9	-	-	None	-	-
RM 125	WF	3.2	-	-	None	-	-
Hall by RM 125	WF	6.1	-	-	None	-	-
RM 124	WF	4.6	-	-	None	-	-
RM 122	SK	<2.5	-	-	None	-	-
RM 123	WF	2.7	-	-	None	-	-
RM 120	WF	<2.5	-	-	None	-	-
RM 121	WF	4.9	-	-	None	-	-
Hall by RM 118	WF	2.7	-	-	None	-	-
RM 118	WF	3.4	-	-	None	-	-
Gym (Left)	WF	<2.5	-	-	None	-	-
Gym (Right)	WF	<2.5	-	-	None	-	-
RM 110	WF	2.6	-	-	None	-	-
RM 112	WF	<2.5	-	-	None	-	-
Women Faculty BR	SK	2.5	-	-	None	-	-
Men Faculty BR	SK	4.6	-	-	None	-	-
Faculty Dinery	SK	<2.5	-	-	None	-	-
Boys LR	SK	2.6	-	-	None	-	-
Girls LR	SK	<2.5	-	-	None	-	-
RM 106	WF	3.9	-	-	None	-	-
RM 108	WF	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 104	SK	2.9	-	-	None	-	-
RM 102	SK	<2.5	-	-	None	-	-
Hall by RM 102	WF	3	-	-	None	-	-
Main Office BR	SK	5.6	-	-	None	-	-
Nurse Office	SK	<2.5	-	-	None	-	-
Nurse Office BR	SK	<2.5	-	-	None	-	-
RM 107	SK	5.2	-	-	None	-	-
WF by RM 107	WF	<2.5	-	-	None	-	-
Boys BR by RM 107	SK	4.1	-	-	None	-	-
Girls BR by RM 107	SK	3.8	-	-	None	-	-
RM 114	SK	118	15	<2.5	FR	Completed FRSLV	5.4
Music Office BR	SK	10	-	-	None	-	-
Hall by RM 226	WF	<2.5	-	-	None	-	-
RM 226	WF	<2.5	-	-	None	-	-
RM 224	SK	7.4	-	-	None	-	-
RM 225	WF	6.8	-	-	None	-	-
RM 222	SK	25	4.9	<2.5	FR	Completed FR	26 (10/17/2016) <1.0 (10/26/2016)
RM 223	WF	<2.5	-	-	None	-	-
RM 221	WF	5.7	-	-	None	-	-
Hall by RM 221	WF	5.4	-	-	None	-	-
RM 220	WF	4.4	-	-	None	-	-
RM 218	WF	3.6	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girls BR by RM 208	SK	<2.5	-	-	None	-	-
RM 208	SK	<2.5	-	-	None	-	-
Hall by School Store	WF	<2.5	-	-	None	-	-
RM 210	SK	<2.5	-	-	None	-	-
Library Office	SK	37	11	5.4	FR	SIGN	-
RM 211	SK	11	-	-	None	-	-
Boys BR by 228	SK	<2.5	-	-	None	-	-
Girls BR by 228	SK	<2.5	-	-	None	-	-
RM 206	SK	<2.5	-	-	None	-	-
Boys BR by RM 204	SK	3.3	-	-	None	-	-
RM 207	SK	<2.5	-	-	None	-	-
RM 202	SK	3.1	-	-	None	-	-
RM 200	SK	<2.5	-	-	None	-	-
Girls BR by RM 203	SK	11	-	-	None	-	-
RM 203	SK	14	-	-	None	-	-
RM 212	SK	<2.5	-	-	None	-	-
WF by RM 202	WF	<2.5	-	-	None	-	-
Art RM	SK	<2.5	-	-	None	-	-
CC SS by Faculty RM	SS	20	<2.5	<2.5	FR	SIGN	-
Kitchen CC	SS	116	<2.5	<2.5	FR	SIGN	-
RM 125	SK	19	<2.5	<2.5	FR	Completed FR	13
RM 124	SK	8.7	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 123	SK	3.8	-	-	None	-	-
RM 121	SK	12	-	-	None	-	-
RM 120	SK	14	-	-	None	-	-
RM 118	SK	11	-	-	None	-	-
RM 108 Class	SK	5	-	-	None	-	-
RM 108 BR	SK	579	<2.5	<2.5	FR	Completed FR	<2.5
RM 106 Class	SK	7.8	-	-	None	-	-
RM 106 BR	SK	34	7.7	<2.5	FR	Completed FR	8
CC SS by RM 106	SS	146	<2.5	<2.5	FR	SIGN	-
RM 110 Class	SK	8.3	-	-	None	-	-
RM 110 BR	SK	578	<2.5	<2.5	FR	CAP	1710 (10/17/2016)
RM 112 Class	SK	2.9	-	-	None	-	-
RM 112 BR	SK	77	<2.5	<2.5	FR	Completed FR	3.9
CC SS Across From Auditorium	SS	<2.5	-	-	None	-	-
CC SS by RM 203	SS	3.7	-	-	None	-	-
RM 201 BR	SK	5.3	-	-	None	-	-
CC SS by RM 208	SS	2.6	-	-	None	-	-
RM 218	SK	170	11	<2.5	FR	Completed FR	24 (10/17/2016) <1.0 (10/26/2016)
RM 220	SK	24	<2.5	<2.5	FR	Completed FR	6.8
RM 223	SK	3.8	-	-	None	-	-
RM 225	SK	11.3	-	-	None	-	-
RM 226	SK	6	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
CC SS by RM 226	SS	4.1	-	-	None	-	-