

CERTIFICATE
OF RESIDENTIAL BURIED FURNACE-FUEL
STORAGE TANK INVESTIGATION
please see attached disclaimer of liability



Customer's Name : **Jodi Graham**
Investigation Site : **2505 Larkin Court, Burnaby, British Columbia**
Legal Description : **Lot 36 Plan NWP21455 District Lot 15 Land District 1 Land District 36**
P.I.D. Number : **002-521-351**

Date of Investigation: **November 24, 2020**
Conducted by: **Special Needs Consulting Service Inc.**
d.b.a. SNR Tank Removal Service


This Company of which I am the President, was incorporated in British Columbia in 1996. Since that time, I have personally conducted more than 1000 buried furnace-fuel storage tank investigations of varying difficulty, in the District of North Vancouver, the Municipality of West Vancouver, and the Cities of Burnaby, New Westminster and Vancouver.

Investigation Results for Inactive Buried Furnace-Fuel Storage Tanks

Investigation has satisfied me that **no buried furnace-fuel storage tank now exists** at the property of the above stated address. Methods employed for this investigation includes;

Visual investigation of the above property
Manual probing of the above property
Electronic metal detection survey of the above property
Canvassing neighbours

Date Issued: **24th day of November 2020.**

Name of Investigator : 
Grandier Sathanielle
SNR Tank Removal Service
6179 Dawson Street
Burnaby, BC V5B 2W5



Certificate of Investigation Disclaimer of Liability

I remove buried furnace-fuel storage tanks as a living; as such it is in my best interest to find a tank when I am called for "detection" services. While I strive to be diligent throughout my investigation, on rare occasion I have missed a buried tank.

I have no insurance to cover the event of an undetected tank through the course of my investigation. As such, I must stress that the SNR Certificate of Investigation is NOT a guarantee of no buried furnace-fuel storage tank existing at a given property.

Also, please note, that while detection service may determine that a buried furnace-fuel storage tank may no longer exist on a given property, had there been one at any time, the SNR investigation can NOT determine the matter of whether contaminated soil may be present.

I appreciate the haunting concern of having a potential liability of significant soil contamination and regret that I am unable to provide my customers with a guarantee regarding these matters.

Yours truly,

A handwritten signature in black ink, appearing to read "Grandt Sathanielle", written over the printed name.

Grandt Sathanielle

SNR Tank Removal Service

Ph: 604-313-8998

Email : snrtankremovalservice@gmail.com