

Ring Power Corporation, 500 World Commerce Pkwy. St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202

←—

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	JMBER	INVOICE D	DATE	CUSTO	MER NO	. CUSTOME	R PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	19	7784	120	#58		01	С	560	2	1
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC	SHIP VIA	D	ATE SH	IPPED	INVOICE S	EQ. NO.
B00458	9	07-23-	19	1A	10	10		01	8 - 27	- 19	43	13516
MAKE	N	ODEL			SERIAL N	UMBER	EQUIPMENT NUMBER	M	ETER RI	EADING	MACH.	ID NO.
AA	D8R		*CA	TOODS	RC6Y	Z01160*	#58		395	. 0	6YZ0	1160
QUANTITY	[4. V	ITEM			N/R		DESCRIPTION		UNIT F	RICE	EXTEN	SION

TRANSPORT MACHINE

DEL OCALA TO HILLIARD 8/15

F/R LBR

1415.00 * 1415.00 T

SEGMENT 00 TOTAL

INSPECT MACHINE

OPERATIONAL AND VISUAL MACHINE EVALUATION, INCLUDING ECM INFORMATION REVIEW, CUSTOM MACHINE CONDITION REPORT, AND ALL COMPARTMENT SOS. ROUTINE MACHINE INSPECTIONS BY EXPERIENCED INSPECTORS CAN HELP UNCOVER PROBLEMS WHICH MAY OTHERWISE BE OVERLOOKED. BACK-UP ALARM, LIGHTS, HORNS, WARNING SYSTEMS, MIRRORS, HOSES, LEAKS ECT.
CHECKED FOR INTEGRITY AND OPERATIONAL PERFORMANCE.
HELPING YOU BE PREPARED FOR PENDING PROBLEMS BEFORE THEY BECOME EXPENSIVE UNSCHEDULED MAJOR FAILURES. ALL MACHINE INSPECTION INFORMATION IS STORED ELECTRONICALLY FOR FUTURE REFERENCE. CUSTOMER COMPLAINT:
INSPECT MACHINE
CAUSE OF FAILURE:

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy. St Augustine. FL 32092, (904) 737-7730

INVOICE 01WC5170202 ←

← P

 Please refer to this number on remittance

SOLD TO

....

SHIP TO

INVOICE N	UMBER	INVOICE D	ATE	CUSTO	MER NO	. CU	STOMER P	URCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	19	7784	120	#5	8		01	C	560	2	2
PSO/WO		DOC. DA	TE	PC	LC	МС		SHIP VIA	D	ATE SH	PPED	INVOICE S	EQ. NO.
B00458	19	07-23-	19	1A	10	10	- 6	6 0	0	B - 27	- 19	43	13516
MAKE		MODEL			SERIAL N	NUMBER		EQUIPMENT NUMBER	M	ETER R	EADING	MACH.	ID NO.
AA	D8R		*CA	TOODS	BRC6Y	Z011	60*	#58		395	. 0	6YZ0	1160
QUANTITY		ITEM			N/R			DESCRIPTION		UNIT	PRICE	EXTEN	SION

RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS:

INSPECT MACHINE

F/R LBR

508.50 *

SEGMENT 01 TOTAL

508.50 T

CLEAN MACHINE

CUSTOMER COMPLAINT:
CLEAN MACHINE
CAUSE OF FAILURE:
CLEAN MACHINE
RESULTANT DAMAGE:
CLEAN MACHINE
REPAIR PROCESS COMMENTS:
CLEAN MACHINE

TOTAL LABOR

SEG. 02

167.20 *

SEGMENT 02 TOTAL

167.20 T

REMOVE & INSTALL TRACK ASSEMBLY
BOTH SIDES

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 600 World Commerce Pkwy, St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202



Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	UMBER	INVOICE I	DATE	CUSTO	MER NO.	CUSTO	WER PU	RCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27	19	7784	20	#58			01	С	560	2	3
PSO/WC	NO.	DOC. DA	TE	PC	LC	MC		ŞHIP VIA	D	ATE SH	IPPED	INVOICE S	EQ. NO.
B00458	19	07-23-	19	1A	10	10	•	70	08	3 - 27	- 19	43	13516
MAKE	N	ODEL			SERIAL N	UMBER		EQUIPMENT NUMBER	М	ETER RI	ADING	MACH.	ID NO.
AA	D8R		*CA	T00D8	RC6Y2	201160	*	#58		395	. 0	6 Y Z 0	1160
QUANTITY	*****	ITEM		100	V/R	1. 1.5	D	ESCRIPTION		UNIT F	RICE	EXTENS	SION

REPAIR PROCESS COMMENTS:
I PULLED MACHINE INTO SHOP AND JACKED UP AND PUT
ON STANDS. I UNBOLTED MASTER TRACK SHOE OFF EACH
SIDE AND PULLED TRACKS OFF MACHINE. I PUSHED
TRACKS BACK UNDER MACHINE AND PULLED AROUND
IDLERS AND SPROCKETS. I CONNECTED TRACKS BACK
TOGETHER AND BOLTED MASTER TRACK SHOES BACK ON
AND TIGHTENED MASTER BOLTS TO SPECS. 3549 AND
3217

4	6V-1724	BOLT	S	4.57	18.28
4	6V-1725	00000 BOLT 00000	S	6.21	24.84

TOTAL PARTS SEG. 03 43.12 *

F/R LBR 621.50 *
SEGMENT 03 TOTAL 664.62 T

REMOVE & INSTALL TRACK LINK ASSEMBLY (S&L)
SEAL

CLEAN ALL PARTS AND REPLACE SEALS

RESULTANT DAMAGE: SEALS IN TRACKS LEAKING OIL.

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy. St Augustine, FL 32092, (804) 737-7730

INVOICE 01WC5170202



Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE NU	IMBER	INVOICE D	DATE	CUSTO	OMER NO.	CUSTO	MER PU	RCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	19	7784	120	#58			01	C	560	2	4
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC		SHIP VIA	D	ATE SH	IPPED	INVOICE S	EQ. NO.
B00458	9	07-23-	19	1A	10	10	11		0	8 - 27	- 19	43	13516
MAKE	N	ODEL			SERIAL N	UMBER	723	EQUIPMENT NUMBER	M	ETER R	EADING	MACH.	ID NO.
AA	D8R		*CA	TOODS	BRC 6 Y	Z01160	*	#58		395	. 0	6YZ0	1160
QUANTITY	1	ITEM	-76	1	N/R	4 44	DE	SCRIPTION		UNIT	RICE	EXTEN	SION

REPAIR PROCESS COMMENTS: I PULLED TRACKS UP ONTO TRACK PRESS BED AND UNBOLTED AND REMOVED TRACK SHOES WITH CLAMP AND OVER HEAD CRANE. I SET TRACK SHOES ON BENCH. I PULLED LINK ASSEMBLIES UP ONTO TRACK PRESS AND PRESSED APART. I TOOK ALL OLD SEALS OUT OF LINKS AND CLEANED LINKS AND PUT NEW SEALS IN LINKS. I DRILLED OUT ALL OLD STOPPERS OUT OF PINS. I WASH OUT ALL PINS ANDINSTALLED ALLL NEW STOPPERS. I CLEANED ALL BUSHING. I PUT PINS BACK INTO BUSHINGS AND PRESSED LINK ASSEMBLIES BACK TOGETHER AND RE OILED PIN AND BUSHINGS. I SET TRACK SHOES BACK ON AND PUT GREASE ON BOLTS AND REPLACED 10 BOLTS AND NUTS THAT WERE MISSING.STARTEDD ALL BOLTS AND NUTS. I TIGHTENED ALL BOLTS AND NUTS TO SPECS. 3217 6.59 26.36 3T · 9118 RING 00000 S 4.09 40.90 10 6V-1723 **BOLT** 00000 20.00 S .20 100 PLUG 6Y-0473 .00000 .39 34.32 **STOPPER** 88 7G-4332 00000 1.50 15.00 10 7G-6442 NUT 00000 1504.98 752.49 272-6013 SEAL SET 00000

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



At No.

Ring Power Corporation 6200 North US 301/441 Ocala, FL 34475 (352) 732-2800

Ring Power Corporation, 500 World Commerce Pkwy. St Augustine. FL 32092, (904) 737-7730

1NVOICE 01WC5170202



Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	JMBER	INVOICE D	DATE	CUSTO	MER NO	. CL	ISTOMER P	JRCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	19	7784	20	#5	8		01	С	560	2	5
PSO/WO	NO.	DOC. DA	TE	. PC	LC	MC		SHIP VIA	, D	ATE SH	IPPED	INVOICE S	EQ. NO.
B00458	9	07-23-	19	1A	10	10			01	B - 27	- 19	43	13516
MAKE	V. T.	ODEL	= -/2	T E	SERIAL	NUMBER	THE R	EQUIPMENT NUMBER	M	ETER R	EADING	MACH.	ID NO.
AA	D8R		*CA	TOODS	RC6Y	Z011	60*	#58		395	. 0	6YZ0	1160
QUANTITY	10	ITEM			N/R	ZIVE.	tion of	ESCRIPTION		UNIT I	RICE	EXTEN	SION

TOTAL PARTS

SEG. 04

1641.56 *

F/R LBR

3390.00 *

SEGMENT 04 TOTAL

5031.56 T

INSTALL PRODUCT LINK SYSTEM PL240B

INSTALL PL240

CUSTOMER COMPLAINT:

MACHINE NEEDS PRODUCT LINK INSTALLED

CAUSE OF FAILURE:

NONE

RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS:

MACHINE WAS BROUGHT INTO THE SHOP AND PRODUCT LINK

WAS INSTALLED ON BEHIND THE DASH PANEL.

REPAIR PROCESS COMMENTS:

3549 &3217 REMOVE AND INSTALL TRACKS.

10	115-8109	SPLICE 00000	S	2.87	28.70
4	199-9785	WIRE AS-SPLI	S	6.55	26.20
1	526-3054	00000 INSTL GP-FIE 00000	S	195.57	195.57

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 600 World Commerce Pkwy, St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202 ←

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	JMBER	INVOICE	DATE CUSTOMER NO.		CUSTON	CUSTOMER PURCHASE ORDER NUMBER			DIV	SALESMAN	TERMS	PAGE	
01WC51	70202	08-27-	19	7784	20	#58			01	С	560	2	6
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC	¥	SHIP VIA	D	ATE SH	PPED	INVOICE S	EQ. NO.
B00458	9	07-23-	19	1A	10	10			0	3 - 27	- 19	43	13516
MAKE	N	ODEL		a PS	SERIAL N	UMBER		EQUIPMENT NUMBER	M	ETER R	ADING	MACH.	
AA	D8R		*CA	TOODS	RC 6 Y	201160		#58		395	. 0	6YZ0	1160
QUANTITY		ITEM			N/R		DE	SCRIPTION		UNIT F	RICE	EXTEN	SION

TOTAL PARTS

SEG. 05

250.47 *

F/R LBR

226.00 *

SEGMENT 05 TOTAL

476.47 T

TROUBLESHOOT ENGINE

T/S ENGINE FOR FUEL IN THE OIL.ENGINE OIL SAMPLE CAME BACK POOR.HIGH FUEL DILUTION OF 22.69%

CUSTOMER COMPLAINT:
ENGINE HAS FUEL IN THE OIL
CAUSE OF FAILURE:
NO LEAK WAS FOUND
RESULTANT DAMAGE:
NO LEAK WAS FOUND.
REPAIR PROCESS COMMENTS:
TROUBLESHOOTING PROCEDURE WAS LOOKED UP ON SIS WEB
AND THE NECESSARY STERS WERE TAKEN TO REMOVE THE
FUEL TRANSFER PUMP AND PRESSURIZE THE FUEL SYSTEM
TO LOOK A LEAK ON THE SHAFT SEAL. NO LEAK WAS
FOUND AND THE PUMP WAS INSTALLED ON THE ENGINE.
AFTER THIS, THE NEXT PROCEDURE WAS TO REMOVE THE
VALVE COVER AND CHECK THE INJECTORS FOR A LEAK.
TO REMOVE THE VALVE COVERS, THE AIR INTAKE AND
THE CROSS OVER BRACKET FOR THE FILTER CANISTER

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy. St Augustine, FL 32092, (904) 737-7730

INVOICE

01WC5170202 <

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	UMBER	INVOICE (DATE	CUSTO	MER NO	. CUSTOME	R PURCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	7-19 778420 #58			01	С	560	2	7		
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC	SHIP VIA	_ D	ATE SH	IPPED !	INVOICE S	EQ. NO.
B00458	39	07-23-	19	1 A	10	10		0.8	8 - 27	-19	43	13516
MAKE	i i i i i i	ODEL			SERIAL N	UMBER	EQUIPMENT NUMBER	M	ETER R	EADING	MACH.	ID NO.
AA	D8R		*CA	TOODS	RC6Y	Z01160*	#58		395	. 0	6YZ0	1160
QUANTITY		ITEM	-	1.	N/R		DESCRIPTION		UNIT	PRICE	EXTEN	SION

WERE REMOVED. NO LEAK WAS FOUND WHEN LOOKING AT INJECTORS AND MACHINE WAS PUT BACK TOGETHER.

1 7W-0688

GASKET 00000

2.98

2.98

TOTAL PARTS

SEG. 06

2.98 *

F/R LBR

1356.00 *

SEGMENT 06 TOTAL

1358.98 T

REMOVE & INSTALL ST CL & BRAKE CONT LINES

REMOVE AND REPLACE STEERING MOTOR HOSES

CUSTOMER COMPLAINT:

REMOVE AND REPLACE STEERING HOSES

CAUSE OF FAILURE:

CAN BE SUSCEPTIBLE TO DAMAGE AND WEAR

RESULTANT DAMAGE:

NONE -----

REPAIR PROCESS COMMENTS: OLD HOSES WERE INSPECTED, REMOVED FROM MACHINE AND

REPLACED WITH NEW HOSES THAT WERE CONSTRUCTED IN

HOUSE.

2 1P-3703

SEAL

2.17

4.34

00000

2 1P-3704

SEAL 00000

S

2.49

4.98

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.


PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy, St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202



SOLD TO

SHIP TO

INVOICE N	JMBER	INVOICE D	DATE	CUSTO	MER NO.	CUST	OMER PU	CHASE ORDER	NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE		
01WC51	70202	08-27-	19	7784	20	#58				01	C	560	2	8		
PSO/WO	NO.	DOC. DA	TE	PC	LC	MC		SHIP VIA		D	ATE SH	PPED	INVOICE SEQ. NO.			
B00458	9	07-23-	3-19 1A 10 10							0	08-27-19			4313516		
MAKE		ODEL			ERIAL N	UMBER	100	EQUIPMENT	NUMBER	M	ETER RE	ADING	MACH. ID NO.			
AA	D8R		*CA	T00D8	RC 6 Y 7	20116	0 *	#58			395	. 0	6YZ01160			
QUANTITY	1	ITEM	-	1.	I/R		DE	SCRIPTION			UNIT F	RICE	EXTEN	ISION		
1 3	E-8857		0	SWI	ГСН А		1	N		65.56		65.				
1 1	56-6287		0	PAN	EL AS	- I	1	V	6	09.43		609	. 43			
1 1	59-4712			FIL	M-IDE	NT	1	N		20.98		20	. 98			
1 1	59-4713				M-IDE	NT	-	N		59.31		59	. 31			
76 4	56-8495		•		E BK-	CM		S		.90		68	. 40			
1 4	96-2313				PLING	AS		S		59.54		59	. 54			
1 4	96-2319				PLING	AS		N		57.54		57	. 54			
3 4	96-9733			0000 COU	PLING	AS		N		53.68		161	. 04			
					TOTAL	. PART	S	SEG.	. 07			1111	.12 *			
					TOTAL	. LABO	R	SEG.	. 07		ŝ	721	.00 *			
2.00	· · · · · · · · · · · · · · · · · · ·		8.0		HOSE	BUILE)	(00000		2	70	.00			
					TOTAL	. MISC	CHGS	SEG	. 07			70	.00 *			
					SEGN	MENT C	7 T OT	AL				1902	.12 T			

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy. St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	UMBER	INVOICE D	DATE	CUSTOMER NO.			TOMER PL	JRCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS !	PAGE
01WC51	170202	08-27-	19	778	778420 #58		3		01	С	560	2	9
PSO/WC	NO.	DOC. DA	TE	PC	LC	MC		SHIP VIA	D	ATE SH	IPPED	INVOICE S	EQ. NO.
B00458	39	07-23-	19	1 A	10	10	-W		0.	8 - 27	.19	43	13516
MAKE	N	ODEL			SERIAL N	UMBER	3	EQUIPMENT NUMBER	M	ETER RI	EADING	MACH.	
AA	D8R		*CA	TOOD	BRC6Y	Z011	50*	#58		395	. 0	6YZO	1160
QUANTITY	2. =	ITEM			N/R		D	ESCRIPTION		UNIT F	PRICE	EXTEN:	SION

REMOVE & INSTALL FAN DRIVE

REMOVE AND REPLACE FAN MOTOR HOSES

CUSTOMER COMPLAINT:

CUSTOMER BROUGHT IN A FLEXAIRE FAN TO INSTALL ON

THE MACHINE.

CAUSE OF FAILURE:

NONE

RESULTANT DAMAGE:

NONE.

REPAIR PROCESS COMMENTS: CUSTOMER BROUGHT IN A FLEXAIRE FAN KIT TO INSTALL ON MACHINE. KIT WAS A GENERIC KIT AND LINES AND A JUMPER HARNESS HAD TO BE MADE. TWO BRACKETS WERE FABRICATED TO HOLD THE VALVE BLOCK AND SOLENOID, AND ALSO TO HOLD THE ELECTRONIC CONTROL BOX. PANELS HAD TO BE REMOVED FROM MACHINE AND CAB ALSO HAD TO BE STRIPPED IN ORDER TO TAP INTO THE PILOT OPERATED SYSTEM TO RUN LINES TO THE VALVE BLOCK. TEE FITTINGS WERE PUT INTO A PRESSURE LINE AND A RETURN LINE IN THE PILOT SYSTEM. UPON REMOVING THE HYDRAULIC OIL COOLER AND THE A/C CONDENSER, WE FOUND THAT THE NEW FAN ASSEMBLY WOULD NOT FIT WITHOUT TAKING THE SAND GRID OUT AS WELL. THE OLD FAN AND FAN HUB WERE REMOVED. THE NEW FAN HUB AND DRIVE ASSEMBLY WERE INSTALLED ON THE MACHINE. THE FAN BLADES WERE INSTALLED AND

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy, St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE NU	JMBER	INVOICE D	ATE	CUSTO	OMER I	NO.	CUSTO	MER PL	IRCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	19	7784	778420 #		#58			01	С	560	2	10
PSO/WO	NO.	DOC. DA	TE	PC	LC	e I	MC	- E	SHIP VIA	D	ATE SH	PPED	INVOICE S	EQ. NO.
B00458	9	07-23-	1.9	1 A	10)	10	966		0	8 - 27	- 19	43	13516
MAKE		IODEL			SERIA	L NU	MBER		EQUIPMENT NUMBER	M	ETER R	ADING	MACH.	ID NO.
AA	D8R		*CA	TOOD	BRCE	5 Y Z	01160	*	#58		395	. 0	6YZ0	1160
QUANTITY		ITEM		· 1	*N/R				ESCRIPTION		UNIT F	RICE	EXTEN	SION

TORQUED TO FLEXAIRE SPECIFICATIONS. THE LINE FOR THE FAN ASSEMBLY WAS RAN IN A NEUTRAL CURVE AND A HOLE WAS DRILLED TO BRING IT THROUGH THE SHROUD. ALL OF THE HOSES AND ELECTRICAL LINES WERE INSTALLED ON THE RIGHT OF THE MACHINE. FOR POWER TO THE CONTROL BOX, I TAPPED INTO THE KEY SWITCH POWER AND USED AN INLINE FUSE FOR FAN POWER BEHIND THE DASH. THE CIRCUIT IS GROUNDED BEHIND THE DASH AS WELL. AFTER INSTALLING FAN AND ALL LINES, FAN WAS TESTED AND WAS OPERATING CORRECTLY. ALL PANELS AND COMPONENTS WERE RE-INSTALLED ON THE MACHINE, MACHINE WAS TESTED AND OPERATED PROPERLY. 2.24 1.12 CAP SCREW S 2 0S-1587 00000 3.46 S 1.73 **0S-1604** BOLT 00000 .34 . 68 S 2 2D-6235 NUT 00000 23.18 S 23.18 **VEE BELT** 25-9506 00000 .21 4.20 S 20 3S-2093 TIE 00000 29.73 29.73 VEE BELT 4N-8218 1 00000

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

S

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

00000

00000

WASHER-HARD

LOCKNUT

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	layer.

Remit to:

.66

.37

Ring Power Corporation PO Box 935004 Atlanta, GA 31193-5004

2.64

1.48

5P-8245

6V-7743



Ring Power Corporation, 500 World Commerce Pkwy. St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE N	UMBER	INVOICE D	DATE	CUSTON	VER NO.	CUST	OMER PU	RCHASE ORDER NUMBER	STORE	DIV	SALESMAN	TERMS	PAGE
01WC51	70202	08-27-	19	7784	20	#58			01	С	560	2	11
PSO/WC	NO.	DOC. DA	TE	PC	LC:	MC		SHIP VIA	D	ATE SH	PPED	INVOICE S	EQ. NO.
B00458	39	07-23-	1.9	1 A	10	10	1480		0	8 - 27	- 19		13516
MAKE	N	ODEL		S	ERIAL N	UMBER		EQUIPMENT NUMBER	N.	ETER RE	MACH.	ID NO.	
AA	D8R		*CA	T00D81	RC6Y	Z0116	0 *	#58		395	. 0	6 Y Z O	1160
QUANTITY	1	ITEM		°N	/R		DE	SCRIPTION		UNIT P	RICE	EXTEN	SION
6 6	V-8397			SEAL				S	1.01		6.	06	
			0	0000									
2 6	V-9836		•	TEE				S	30.89		61.	. 78	
4 8	T-4205		U	0000 Wasi	IED			S	. 29		1	. 16	
7 0	1-4203		0	0000	ILK		•	3	. 23			. 10	
2 8	T-9367			BOL1			:	S	. 43			86	
			0	0000	_			_					
2 9	S·1366		BOLT					S	1.57		3.	. 14	
2 9	X-0941		U	0000 NUT			(S	2.19		4	38	
2 3	V-034I		0	0000			,	•	2.13		т.	. 50	
2 9	X-3401		·	PIN.	CONN	ECTOR	MALE	S	1.30		2.	. 60	
			0	0000				_					
2 9	X-3402		0		KET, F	EMALE		S	1.67		3.	. 34	
4 9	X-8267		U	0000 Wasi	IFR			S	. 26		1.	. 04	
7 3	N-0207		0	0000	ILIX			•			•		
1 1	02-8802		·		TACL	E KI		S	4.03		4.	. 03	
			0	0000				_			_		
3 1	15-8109			SPLI	CE		ı.	S	2.87		8.	. 61	9
6 1	26-1767		U	0000 PIN				S	1.58		9	48	
0 1	20-1707		0	0000				•	1.50		,		
6 1	26-1768		_	SOCK	(ET		1	S	1.92		11	. 52	
			0	0000								7.4	
1 1	29-2416		V-BELT SET					N :	114.74 114.74				
1 1	55-2270		00000 PLUG KIT					S	4.19 4.19				
1 1	33-22/0		0	0000	2 KII			•	7.13		7		

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation. 500 World Commerce Pkwy. St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE NU	JMBER	INVOICE	DICE DATE CUSTOMER N		MER NO.	CUST	OMER PUR	CHASE ORDER NUM	BER	STORE	DIV	SALESMAN	TERMS	PAGE	
01WC5170202		08-27	- 19	778420		#58	#58			01	С	560	2	12	
PSO/WO NO. DO		DOC. DA	ATE PC LC		MC	MC SHIP VIA		5	DATE SHIPPED		PPED	INVOICE SEQ. NO.			
B004589 07-2		07-23	1:9	1A -	10	10	10			08-27-19			4313516		
MAKE MODEL			Mora.		SERIAL N	JMBER	HOLES BEIN	EQUIPMENT NUMBER			ETER RE	ADING	MACH. ID NO.		
AA D8R			*CATOOD8RC6YZ01160*					#58	58			395.0		6YZ01160	
QUANTITY				.1	V/R	4.5	DE	DESCRIPTION			UNIT PRICE		EXTENSION		
1 20	7-3814		0	WIR 0000	E AS.	-SPL	Ş			7.47			. 47		
2 32	23 - 6167		COUPLING AS-					5		19.42 3			. 84		
2 32	2 323-6181		COUPLING · PER				9	5	14.26			28	18.52		
662 45	62 456-8466			HOSE BK				5	. 24 15			158	. 88		
1 82	2-2208		0	FUS 0000	E HOL	DER	5	5		4.73		4	. 73		
					TOTAL	PART	s	SEG. 08				542	.98 *		
3.50 2.00					R134 HOSE	FREON BUILD		F/R L 0000 0000	0			62	.00 * .58 .00		
				T.	TOTAL	MISC	CHGS	SEG. 08	1			132	.58 *		
					SEGM	ENT 0	8 TOT	NL				3387	.56 T		

PERFORM PM 4

CUSTOMER COMPLAINT: PERFORM PM 4 CAUSE OF FAILURE: NONE

Servicing All Makes All Models of Trucks, RVs & Buses, Comments? www.rptrucks.com/feedback

The second control of the second control of

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy, St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202 ←

Please refer to this number on remittance

SOLD TO

SHIP TO

INVOICE NUMBER		INVOICE D	INVOICE DATE		OMER NO.	. CUSTOMER PURCHASE ORDER NUMBER			STORE	DIV	SALESMAN	TERMS	PAGE	
01WC5170202		08-27-	-19 778420		#58			01	С	560	2	13		
PSO/WC	PSO/WO NO.		TE	PC LC		MC	SHIP VIA		DATE SHIPPED		IPPED	INVOICE SEQ. NO.		
B00458	B004589		19	1A 10 10		W-3.5	936 E S E		08-27-19		4313516			
MAKE					UMBER	MBER EQUIPMENT NUMBER			METER READING			MACH, ID NO.		
AA	D8R		*CA	T00D8RC6YZ01160*				#58		395.0			6YZ01160	
QUANTITY	1	ITEM		*N/R				SCRIPTION	- 1	UNIT F	PRICE	EXTENS	SION	

RESULTANT DAMAGE:

NONE

REPAIR PROCESS COMMENTS:

A PM 4 WAS PERFORMED ON THE MACHINE, ALL FILTERS

WERE REPLACED. ENGINE OIL WAS CHANGED.

TRANSMISSION FLUID WAS CHANGED, BOTH FINAL DRIVE

FLUIDS WERE CHANGED AND THE MACHINE WAS GREASED. ENGINE WAS TEST RAN AND EVERYTHING IS WORKING

PROPERLY.

540.33 * F/R PTS F/R LBR 960.00 * 1266.31 * F/R MSC 2766.64 T

SEGMENT 09 TOTAL

REMOVE & INSTALL DASH

REMOVE AND INSTALL DASH BEZEL

CUSTOMER COMPLAINT:

DASH IS BROKE

CAUSE OF FAILURE:

THE PLASTIC GOT OLD AND DRY-ROTTED

RESULTANT DAMAGE:

THE PIECES THAT HOLD THE DASH ON BROKE REPAIR PROCESS COMMENTS:

WHEN I WAS TAKING THE DASH APART TO INSTALL THE PRODUCT LINK, I FOUND THAT THE MOUNTING SOCKETS

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.


PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

Remit to:



Ring Power Corporation, 500 World Commerce Pkwy, St Augustine, FL 32092, (904) 737-7730

INVOICE 01WC5170202



SOLD TO

SHIP TO

INVOICE NUMBER INVOICE		I INVOICE D	DATE CUSTOMER NO.		. CUSTOMER PURCHASE ORDER NUMBER			STORE	DIV	SALESMAN	TERMS	PAGE		
01WC5170202		08-27-	-27-19 7		778420				01	С	560	2	14	
PSO/WO NO.		DOC. DA		PC LC		#58 MC	1301	SHIP VIA		DATE SHIPPED		INVOICE SEQ. NO.		
B00458	B004589		1.9	1 A	10	10	10 ~ .		- 0	08-27- 1 9		4313516		
MAKE MODEL				25 72	SERIAL N	UMBER		EQUIPMENT NUMBER	M	METER READING			MACH. ID NO.	
AA	DBR		*CAT	T00D8RC6YZ01160*				#58	395.0			6YZ01160		
QUANTITY		ITEM		7	N/R		D	ESCRIPTION	UNIT PRICE			EXTEN	SION	

FOR THE DASH WERE BROKE. THE DASH BEZEL NEEDED TO BE REPLACED. A NEW DASH BEZEL AND IDENTIFICATION STICKERS WERE ORDERED TO REPLACE THE BEZEL. ALL COMPONENTS WERE TRANSFERRED FROM THE OLD DASH TO THE NEW DASH.

TOTAL LABOR

SEG. 11

271.20 *

SEGMENT 11 TOTAL

271.20 T

ENVIRO/MISC

300.00 T

AMOUNT
TAX EXEMPTION LICENSE FL GA AG EXEMPT

18249.85

"TERMS NET 30 DAYS FROM DATE OF INVOICE"
PLEASE CALL 352-732-2800 IF YOU HAVE QUESTIONS CONCERNING THIS INVOICE

Servicing All Makes All Models of Trucks, RVs & Buses. Comments? www.rptrucks.com/feedback

ALL MERCHANDISE SUBJECT TO RETURN ONLY AFTER PERMISSION HAS BEEN REQUESTED AND APPROVED. RETURNED MATERIAL IS SUBJECT TO A HANDLING CHARGE AND MUST BE SENT IN PREPAID EXCEPT IN THOSE CASES WHERE PARTS ARE SHIPPED IN ERROR. IN SUCH CASES HANDLING CHARGE IS WAIVED AND RETURN MAY BE EFFECTED ON A FREIGHT COLLECT BASIS.

PAY THIS AMOUNT	18249.85
AMOUNT CREDITED	

Remit to: