



Custom Track Service Summary

THOMPSON TRACTOR

SOUTHLAND RESOURCES (7279300)

Prepared By: Donnie Wright

Model	D11R	Job Site	--	Inspection Date	17Aug20
Manufacturer	Caterpillar		<u>Left</u> <u>Right</u>	Next Inspection Date	--
Serial Number	7PZ00566	Track Sag (6.1 in - 6.9 in)	-- --	Next Inspection Hours	--
Reference Number	436	Frame Ext (max 7.8 in)	6.50 " 5.90 "	<u>Underfoot Conditions</u>	
Hour Meter Reading	--	Dry Joints	-- --	Impact	Moderate
Hours Per Week	--	Internal Wear	50.10 " 50.10 "	Abrasion	Moderate
<u>Total Odometer Reading</u>	--		10% 10%	Moisture	Moderate
Forward Odometer	--	Track Shoe Width	28.00 " 28.00 "	Packing	Moderate
Reverse Odometer	--			Bushing Allowable Wear	Greater
				Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% WORN		PROJECTED SMU AT 100%		PROJECTED SMU AT 120%		PROJECTED DATE AT 100%		PROJECTED DATE AT 120%	
TRACK LINK	Monitor	56% (1.94 in)	74% (1.80 in)	--	--	--	--	--	--	--	--
TRACK BUSHING	Monitor	64% (0.60 in)	21% (0.75 in)	--	--	--	--	--	--	--	--
NOTES: Not Turned				NOTES: Not							
TRACK SHOE	Monitor	50% (3.61 in)	40% (3.95 in)	--	--	--	--	--	--	--	--
FRONT IDLER	Monitor	98% (1.40 in)	78% (1.20 in)	--	--	--	--	--	--	--	--
REAR IDLER	Monitor	98% (1.40 in)	88% (1.30 in)	--	--	--	--	--	--	--	--
TRACK ROLLER FRONT	Monitor	50% (2.21 in)	98% (1.53 in)	--	--	--	--	--	--	--	--
2	Replace	62% (2.06 in)	117% (1.06 in)	--	--	--	--	--	--	--	--
3	Monitor	94% (1.64 in)	72% (1.95 in)	--	--	--	--	--	--	--	--
4	Monitor	74% (1.91 in)	54% (2.19 in)	--	--	--	--	--	--	--	--
5	Monitor	72% (1.93 in)	48% (2.24 in)	--	--	--	--	--	--	--	--
6	Monitor	77% (1.87 in)	55% (2.18 in)	--	--	--	--	--	--	--	--
7	Monitor	89% (1.72 in)	46% (2.25 in)	--	--	--	--	--	--	--	--
8	Replace	112% (1.19 in)	90% (1.71 in)	--	--	--	--	--	--	--	--
SPROCKET	Monitor	70% (13.00 in)	76% (12.90 in)	--	--	--	--	--	--	--	--

General Recommendations

--