



Custom Track Service Summary

MUSTANG SALES & SERVICE CO., LLC. (E300)

TEXAS MUNICIPAL PWR AGENCY

Prepared By: JACKSON GEROW

Model	D10T	Job Site	--	Inspection Date	05May21
Manufacturer	Caterpillar		<u>Left</u> <u>Right</u>	Next Inspection Date	--
Serial Number	RJG01339	Track Sag (5.7 in - 6.5 in)	-- --	Next Inspection Hours	--
Reference Number	--	Frame Ext (max 7.6 in)	-- --	Underfoot Conditions	
Hour Meter Reading	--	Dry Joints	0 0	Impact	--
Hours Per Week	--	Track Shoe Width	30.90 " 30.90 "	Abrasion	--
Total Odometer Reading	--			Moisture	--
Forward Odometer	--			Packing	--
Reverse Odometer	--			Bushing Allowable Wear	Greater
				Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% WORN		PROJECTED SMU AT 100%	PROJECTED SMU AT 120%	PROJECTED DATE AT 100%	PROJECTED DATE AT 120%
TRACK LINK	Good	0% (2.36 in)	2% (2.35 in)	--	--	--	--
BUSHING (EXT)	Good	8% (0.70 in)	4% (0.71 in)	--	--	--	--
TRACK SHOE	Good	11% (4.28 in)	10% (4.30 in)	--	--	--	--
FRONT IDLER	Good	28% (0.92 in)	24% (0.90 in)	--	--	--	--
REAR IDLER	Good	24% (0.90 in)	24% (0.90 in)	--	--	--	--
TRACK ROLLER FRONT	Good	7% (2.78 in)	7% (2.78 in)	--	--	--	--
2	Good	8% (2.77 in)	6% (2.79 in)	--	--	--	--
3	Good	3% (2.62 in)	3% (2.62 in)	--	--	--	--
4	Good	2% (2.63 in)	2% (2.63 in)	--	--	--	--
5	Good	2% (2.63 in)	2% (2.63 in)	--	--	--	--
6	Good	2% (2.63 in)	2% (2.63 in)	--	--	--	--
7	Good	6% (2.79 in)	6% (2.79 in)	--	--	--	--
8	Good	7% (2.78 in)	7% (2.78 in)	--	--	--	--
SPROCKET	Good	--	--	--	--	--	--

CONDITION: Good

CONDITION: Good

General Recommendations
--