

ZX330-6 Hydraulic Shovel

2023/07/26

BASIC INFORMATION

Inspection Date	2023/07/25	Model	ZX330-6	Serial No.	81715
Date of Manufacture		Hourmeter	2564 HR	Condition of Hourmeter	HR is normal
Hourmeter (Estimated)		Engine No.		Job Status	Rental
Accident History		Cabin/Canopy	Cabin	Cabin Type	ROPS
Front Attachment	Standard	Super long length(m)		Type of Shoe	Grouser
Width of Track Shoe	600	Bucket/Attachment	Standard BK	Stamp	
Others	EPA, Air Conditioner, Multi Lever, Piping				

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Slight	Traveling	Normal	Front Attachment	Normal
Pump Device	Normal				

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread(Right)	Slight	Wear: Track Link Tread(Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Slight	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Broken/Crack: Rubber Shoe(Right)		Broken/Crack: Rubber Shoe(Left)		Missing: Rubber Shoe Core	
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler(Right)	Slight	Wear: Front Idler(Left)	Slight
Wear: Sprocket(Right)	Slight	Wear: Sprocket(Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Boom	Normal	Arm	Normal	Wear: Boom Foot Pin	Slight
Wear: Boom/Arm Joint Pin	Slight	Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear/Deformation: Bucket	Good	Wear/Deformation: Blade			

OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder(Right)	No	Oil Leak: Boom Cylinder(Left)	No
Oil Leak: Arm Cylinder(Right)	No	Oil Leak: Arm Cylinder(Left)		Oil Leak: Bucket Cylinder(Right)	No
Oil Leak: Bucket Cylinder(Left)		Oil Leak: Offset Cylinder		Oil Leak: Blade Cylinder	
Oil Leak: Engine	No	Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No
Oil Leak: Pilot Valve	No	Oil Leak: Center Joint	No	Oil Leak: Swing Device	No
Oil Leak: Pump Device	No				

APPEARANCE

Engine Cover	Deformed/Dent	Side Covers	Good Condition	Under Covers	Deformed/Dent
Counter Weight	Good Condition	Main frame	Good Condition	D Frame	Good Condition
Track Frame	Good Condition	Cabin	Good Condition	Door	Good Condition

INTERIOR

Cabin Interior	Good Condition	Seat	Good Condition	Console	Good Condition
Air conditioner	Good Condition	Freon gas inspection	Good Condition		

OVERALL RATING

Appearance Evaluation	Good	Rust/Corrosion		Overall Rating	Good
-----------------------	------	----------------	--	----------------	------