

ZX135USK-6 Hydraulic Shovel

2023/08/25

BASIC INFORMATION

Inspection Date	2023/04/20	Model	ZX135USK-6	Serial No.	510062
Date of Manufacture		Hourmeter	2419 HR	Condition of Hourmeter	
Hourmeter (Estimated)		Engine No.		Job Status	Rental
Accident History		Cabin/Canopy	Cabin	Cabin Type	ROPS
Front Attachment	Standard	Super long length(m)		Type of Shoe	Grouser with Pad
Width of Track Shoe	500	Bucket/Attachment	Standard BK	Stamp	
Others	EPA, Air Conditioner, ML Crane, Multi Lever, Piping, Blade				

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Slight	Traveling	Normal	Front Attachment	Normal
Pump Device	Normal				

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread (Right)	Slight	Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Slight	Bent/Broken/Missing: Track Shoe	1~4 Pieces
Wear: Rubber Pad	Moderate/Within Service Limit	Broken/Missing: Rubber Pad	Broken/Missing (Right), Broken/Missing (Left)	Missing: Rubber Pad	None
Broken/Crack: Rubber Shoe (Right)		Broken/Crack: Rubber Shoe (Left)		Missing: Rubber Shoe Core	
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Boom	Deformed/Dent	Arm	Reinforcement	Wear: Boom Foot Pin	Slight
Wear: Boom/Arm Joint Pin	Slight	Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear/Deformation: Bucket	Good	Wear/Deformation: Blade	Good		

OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder (Right)	No	Oil Leak: Boom Cylinder (Left)	No
Oil Leak: Arm Cylinder (Right)	No	Oil Leak: Arm Cylinder (Left)		Oil Leak: Bucket Cylinder (Right)	No
Oil Leak: Bucket Cylinder (Left)		Oil Leak: Offset Cylinder		Oil Leak: Blade Cylinder	
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	Slight Film	Oil Leak: Pilot Pipes	Slight Film
Oil Leak: Pilot Valve	No	Oil Leak: Center Joint	No	Oil Leak: Swing Device	No
Oil Leak: Pump Device	No				

APPEARANCE

Engine Cover	Good Condition	Side Covers	Good Condition	Under Covers	Good Condition
Counter Weight	Scratched	Main frame	Good Condition	D Frame	Good Condition
Track Frame	Good Condition	Cabin	Good Condition	Door	Good Condition

INTERIOR

Cabin Interior	Good Condition	Seat	Dirty	Console	Good Condition
Air conditioner	Good Condition	Freon gas inspection	Good Condition		

OVERALL RATING

Appearance Evaluation	Good	Rust/Corrosion	Slight	Overall Rating	Fair
-----------------------	------	----------------	--------	----------------	------