

ZX75US–5B Hydraulic Shovel

2024/01/09

BASIC INFORMATION

| | | | | | |
|-----------------------|---|----------------------|----------------------------|------------------------|------------------|
| Inspection Date | 2023/11/02 | Model | ZX75US-5B | Serial No. | 072997 |
| Date of Manufacture | 2018/09 | Hourmeter | 3489 HR | Condition of Hourmeter | HR is normal |
| Hourmeter (Estimated) | | Engine No. | | Job Status | |
| Accident History | | Cabin/Canopy | Cabin | Cabin Type | |
| Front Attachment | Standard | Super long length(m) | | Type of Shoe | Grouser with Pad |
| Width of Track Shoe | | Bucket/Attachment | Standard BK, No Attachment | Stamp | |
| Others | Piping, EPA, Air Conditioner, Multi Lever, ML Crane | | | | |

OPERATION

| | | | | | |
|---------------------|--------|-------------------|--------|------------------|--------|
| Engine | Normal | Exhaust Gas Color | Normal | Swing | Normal |
| Wear: Swing Bearing | Slight | Traveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | | | |

UNDERCARRIAGE/CHASSIS/TIRES

| | | | | | |
|----------------------------------|--------|------------------------------------|-------------------------------|-----------------------------------|-------------------------------|
| Seize: Track Links | No | Wear: Track Link Extension (Right) | Moderate/Within Service Limit | Wear: Track Link Extension (Left) | Moderate/Within Service Limit |
| Wear: Track Link Tread(Right) | Slight | Wear: Track Link Tread(Left) | Slight | Wear: Track Link Pins (Right) | Slight |
| Wear: Track Link Pins (Left) | Slight | Wear: Track Shoe/Rubber Shoe | Slight | Bent/Broken/Missing: Track Shoe | No |
| Wear: Rubber Pad | Slight | Broken/Missing: Rubber Pad | No | Missing: Rubber Pad | None |
| Broken/Crack: Rubber Shoe(Right) | No | Broken/Crack: Rubber Shoe(Left) | No | Missing: Rubber Shoe Core | No |
| Wear: Upper Rollers | Slight | Wear: Lower Rollers | Slight | Oil Leak: Rollers | None |
| Broken/Missing: Rollers | None | Wear: Front Idler(Right) | Slight | Wear: Front Idler(Left) | Slight |
| Wear: Sprocket(Right) | Slight | Wear: Sprocket(Left) | Slight | Oil Leak: Travel Device | No |
| Oil Leak: Travel Pipes | No | | | | |

FRONT & PINS

| | | | | | |
|--------------------------|--------|-------------------------|--------|---------------------|--------|
| Boom | Normal | Arm | Normal | Wear: Boom Foot Pin | Slight |
| Wear: Boom/Arm Joint Pin | Slight | Wear: Arm Tip Pin | Slight | Wear: Other Pins | Slight |
| Wear/Deformation: Bucket | Good | Wear/Deformation: Blade | Good | | |

OIL/WATER/AIR LEAK

| | | | | | |
|---------------------------------|----|--------------------------------|----|----------------------------------|----|
| Oil Leak: Front Pipes | No | Oil Leak: Boom Cylinder(Right) | No | Oil Leak: Boom Cylinder(Left) | No |
| Oil Leak: Arm Cylinder(Right) | No | Oil Leak: Arm Cylinder(Left) | No | Oil Leak: Bucket Cylinder(Right) | No |
| Oil Leak: Bucket Cylinder(Left) | No | Oil Leak: Offset Cylinder | No | Oil Leak: Blade Cylinder | No |
| Oil Leak: Engine | No | Oil Leak: Oil Cooler | No | Leak: Radiator | No |
| Leak: Cooling Pipes | No | Oil Leak: Fuel System | No | Oil Leak: Control Valve | No |
| Oil Leak: Low Pressure Pipes | No | Oil Leak: High Pressure Pipes | No | Oil Leak: Pilot Pipes | No |
| Oil Leak: Pilot Valve | No | Oil Leak: Center Joint | No | Oil Leak: Swing Device | No |
| Oil Leak: Pump Device | No | | | | |

APPEARANCE

| | | | | | |
|----------------|----------------|-------------|----------------|--------------|----------------|
| Engine Cover | Good Condition | Side Covers | Good Condition | Under Covers | Good Condition |
| Counter Weight | Good Condition | Main frame | Good Condition | D Frame | Good Condition |
| Track Frame | Good Condition | Cabin | Good Condition | Door | Good Condition |

INTERIOR

| | | | | | |
|-----------------|----------------|----------------------|----------------|---------|----------------|
| Cabin Interior | Good Condition | Seat | Good Condition | Console | Good Condition |
| Air conditioner | Good Condition | Freon gas inspection | Good Condition | | |

OVERALL RATING

| | | | | | |
|-----------------------|-----------|----------------|----|----------------|-------------------------|
| Appearance Evaluation | Excellent | Rust/Corrosion | No | Overall Rating | Quite New(Include DEMO) |
| Special Notes | | | | | |