

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

 LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

 MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE		PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
11/16/10	(11:30 – 12:00)	SITE VISIT -- Problem: Unit blanked out intermittently (missing hours here and there.) Replaced processor.		Hoang		
11/30/10		MODERATE IMPACT US 395 Both Directions - Road Conditions for US 395 from SR 26 to I-90 are: snow covered. From milepost 72 to milepost 102 (Tom)				

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C)
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

 LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

 MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
9/30/10		<b>No Changes</b>			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
8/31/10		<b>No Changes</b>			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7/31/10		<b>No Changes</b>			

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C)
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

 LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

 MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
6/30/10		<b>No Changes</b>			

800.12-11.9-12

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C)
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/31/10		No Changes			

File: 800.12.11.9.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P7C)
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
4/5/10		SITE VISIT -- Hoang -- 1740 - 1755 -- Problem: No loop activation (no data was collected). Cleaned and re-seated PIO72 card.			
4/12/10		Problem: Zero axle detected all lanes (around 08:13 on April 07 <sup>th</sup> ). Did "system shutdown". Site is back to normal for now. It's time to replace the A/D card for this unit (third time this site has done this).			

File: 800.12.11.9.12  
530200

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P7C )
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 0201 ]

LOCATION SR 395 TYPE EQUIP. \_\_\_\_\_

MP # 91.0 MODEL # IRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
3/3/10	1145-1300	Site inspection. Copied log and parameter files. Re-spliced loops #7 and #8. Site looks good! (HN)	HN		