

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P06]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [3813]</p>
---	--

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
12/12/13		Rollover collision on SR 14 westbound at milepost 10.00 just East of 192nd, blocking right lane. Use caution and expect delays. 0652-0750	ROADS db		
12/21/13		Collision on SR 14 eastbound at milepost 10.00 near 192nd exit is blocking the left lane. Use caution in the area. 0333-0413	ROADS db		
12/2/13		del vol WB 6	PP		

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
11/7/13	1100-1800	SR 14, Both directions between SE 164th Avenue and NW 6th Avenue (mileposts 9 to 12) Monday, Nov. 4 to Thursday, Nov. 7: Daytime mobile right-lane closures for brush mowing.	RH		

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10/6/2013 6:00 thru 10/10/2013 18:00		SR 14, Both directions between NE 164th Avenue and NW 6th Avenue (mileposts 8.0 to 12.0) Monday, Oct. 7 to Thursday, Oct. 10: Daytime mobile shoulder closures with slow-moving vehicles for roadside maintenance activities.	RH		
10/17/2013 4:32 – 6:00		A collision on SR 14 eastbound at Milepost 12 near 6th Avenue is blocking the lane, beginning at 4:32 a.m. on October 17, 2013 until approximately 6:00 a.m..	RH		

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

File: 800.12.11.8.12

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7/31/13		Quit at 0200 on 7/31/13			

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

File: 800 12.11.8.12

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7/5-6/2013		Missing Hours 05/0100-06/0100			

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

File: 800.12.11.8.12

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/5/13		Missing data 05/0100 – 06/0100			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID [P06] *STATE CODE [53] *SHRP SECTION ID [3813]
--	--

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
03/22/13		Deployed the new class scheme (WASH2013) East bound drive lane's homerun conduit is exposed again because the cold patch/epoxy is breaking out. (Need to schedule a repair asap before the conduit brakes.)			

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
2/28/13		NO CHANGES			
2/8/13		<p>The driver of a tractor-semitrailer tipped the rig onto its side Tuesday evening trying to avoid a load of hay that was spilled on state Highway 14 at Northwest Alpine Lane in Camas.</p> <p>At 5:45 p.m., a pickup hauling a trailer of hay was heading westbound on Highway 14 when it lost its load, spilling 50 to 80 bales on the roadway, said Trooper Will Finn, spokesman for the Washington State Patrol.</p> <p>Traffic darted to the right shoulder to avoid the hay, including the semi-truck. The truck went too far to the right and tipped onto its side into an embankment, Finn said.</p> <p>No one was hurt in the incident, but the right lane was blocked until about 9 p.m.</p> <p>Names of those involved were not available at The Columbian's press time. Jh</p>			

File: 800.12.11.8.17

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P06]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3813]

LOCATION SR 14 TYPE EQUIP. Piezo (Class 1)

MP # 11.9 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
01/31/13		NO CHANGES			
1/28/13		PROCESSED MANUAL COUNT: on 1-17-13; EB= 0.92%; WB= 1.56%; BWs= 1.29% -- OK -- CP/JH			