

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P19 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 6048 ]</p>
---	--

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		<b>Out of Study</b>			
9/30/11		No Changes			
9/13/11		<p>Tree limb knocks out power in Woodinville Tuesday, September 13th, 2011, 8:46am Approximately 650 people in Woodinville were left without power for a few hours last after a tree limb landed on an overhead power line near Woodinville- Duvall Road. Power was knocked out at 12:08 a.m., and the limb was removed and power restored at 2:50 a.m. (Tom)</p>			
9/26/11		<p>LOW IMPACT SR 522 Eastbound - Monday, Sept. 26 to the morning of Friday, Sept. 30 - Crews will shift lanes and work on the shoulders at the interchange of N.E. 195th Street and Woodinville-Snohomish Road, near SR 522, nightly from 8 p.m. to 5 a.m. The exit ramp from SR 522 will not be closed, but drivers exiting eastbound SR 522 to N.E. 195th Street should be prepared for possible delays. Last Updated: 9/23/2011 7:52 AM At milepost 12 (Tom)</p>			

800-12.11.8.12

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]

800.12.11.8.12

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]

800.12.11.8.12

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P19 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 6048 ]</p>
---	--

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		<b>Out of Study</b>			
<b>3/31/11</b>		<b>No Changes</b>			
3/12/11		<p>SR 522 Direction: W Start <b>Milepost: 12.52</b></p> <p>Main Message: Cleared 5:50 AM : On the SR 522 westbound on-ramp from NE 195th St (MP 13) there is an incident blocking the ramp. Medical Aid, Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene.</p> <p><b>Trooper injured after parked patrol car hit on Highway 522</b> Saturday, March 12th, 08:50am A trooper was injured early Saturday morning after his parked patrol car was hit on Highway 522 near 195th. The Washington State Patrol reports that the trooper was sitting inside his vehicle, which was parked on the left shoulder of the westbound lanes, when a 2002 Toyota RAV4 traveling east on 522 crossed the median and crashed into the patrol car. The impact left both vehicles totaled. The trooper, a 34-year-old man from Monroe, was taken to Evergreen Hospital in Kirkland for treatment of his injuries. The driver of the Toyota, a 22-year-old from Marysville, was unhurt. Both were wearing seat belts. Investigators are still looking into what caused the Toyota to veer across the median and hit the patrol car. No citations have been issued as on Saturday morning.</p>			

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

<p style="text-align: center;">SHEET 15</p> <p style="text-align: center;">LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P19 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6048 ]

LOCATION SR 522 TYPE EQUIP. Piezo (Class 1)

MP # 13.3 MODEL # IRD 1060

[illegible]