

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[ P13 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6056 ]

 LOCATION SR 195 TYPE EQUIP. Piezo (Class 1)

 MP # 6.01 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/31/11		NO CHANGES			
5/10/11		<b>Uniontown-P13</b> Site inspected. Copied log and parameter files. Site looks good! (HN)	hn		

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [ P13 ]</p> <p>*STATE CODE [ 53 ]</p> <p>*SHRP SECTION ID [ 6056 ]</p>
---	--

LOCATION SR 195 TYPE EQUIP. Piezo (Class 1)

MP # 6.01 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
3/31/11		NO CHANGES			
3/1/11		<p>Neighbors fed up with 'Palouse weather' Posted on March 1, 2011 at 4:22 PM ALBION, WA -- More than 15 inches of snow have covered parts of the region in less than 24 hours. Now the entire Palouse region is digging out again Tuesday night.</p> <p>In small towns like Albion it's wet, cold and slushy. KREM 2 News went down there to talk to people who are fed up with the late winter snow. Kimberly Osborn says it's insane that she is clearing roughly 15 inches of snow on the first day of March. This is the second time she has had to dig a path first thing in the morning. Up the road, Nils Nelson is apparently used it it, he calls it "Palouse weather". Meanwhile, Laban Molsee remains optimist. He says there is light at the end of the snow packed tunnel and believes the snow will melt soon.</p> <p>The area also had to deal with a two hour power outage starting around 5 a.m. Tuesday.</p> <p>Note***: Albion is located North of Pullman (Tom)</p>			

File: 800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[ P13 ]
	*STATE CODE	[ 53 ]
	*SHRP SECTION ID	[ 6056 ]

LOCATION SR 195 TYPE EQUIP. Piezo (Class 1)

MP # 6.01 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
2/28/11		NO CHANGES			
2/16/11		<p>MODERATE IMPACT US 195 Both Directions - US 195 from Pullman to Colfax is: Slush and snow covered. From milepost 22 to milepost 44</p> <p>MODERATE IMPACT US 195 Both Directions - US 195 from Idaho State line to Pullman is: Slush and snow covered. From milepost 1 to milepost 20</p>			
2/22/11		<p>Main Message: Collision on US 195 north bound at milepost 7.00 beginning at 2:24 PM on February 22, 2011 until 3:06 PM</p>			