

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P14]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [7322]</p>
---	--

LOCATION SR 195 TYPE EQUIP. Piezo (Class 1)

MP # 22.2 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10-16-02	(08:10-08:25)	<p>Pullman P14 Was: Needs calibrating after piezo leveling. Action: Found temp sensor hooked up but, not installed in road. Was lying in bottom of cabinet. Will calibrate after installation is complete. (RCR) Note***: temporary sensor was put in cabinet\ 2-27-02.</p>	(Tom)		
12/11/02		<p>Pullman P14. Temp.sensor from road in cabinet. Removed temporary sensor connected inside cabinet and connected road temperature sensor. Had to find correct wiring order. Tested.</p>	(KL)		

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P14]
	*STATE CODE	[53]
	*SHRP SECTION ID	[7322]

LOCATION SR 195 TYPE EQUIP. Piezo (Class 1)

MP # 22.2 MODEL # IRD 1060[illegible]

MP # 22.2 MODEL # IRD 1060

[illegible]

<p align="center">SHEET 15</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P14]
	*STATE CODE	[53]
	*SHRP SECTION ID	[7322]

LOCATION SR 195 TYPE EQUIP. Piezo (Class 1)

MP # 22.2 MODEL # IRD 1060

[illegible]