

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P08]
	*STATE CODE	[53]
	*SHRP SECTION ID	[7409]

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10-5-05	07:00- 16:00	Buena P08 Replaced loops 7 & 8 and piezo # 6. Spliced loops at j-box and terminated piezo in cabinet. Didn't install conduit across westbound lanes because we didn't have enough single pair wire.	(RCR)		
10/19/05	12:00 - 13:00	10/19/05 P08 Buena Checked site's configurations. Inspected site. Balanced sensors lane #3. Copied log and parameter files.	(HN)		