

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P08]
	*STATE CODE	[53]
	*SHRP SECTION ID	[7409]

File: 800.12.11.8.12

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
12/31/12		No changes			
12/28/12		ROADS Event InformationType: Closure Event ID: 124187 Source System: RadioLog System ID: 598160 Priority: Medium Status: Closed Publish Date: 12/28/2012 6:51:00 PM Last Modified: 12/28/2012 10:10:43 PM Remove Date: 12/28/2012 10:30:00 PM Modified By: WSDOTMerediG Region: South Central Location Information: Road State Route: 082 Direction: W Start Milepost: 40.00 Ahead Back: Start Landmark: End Milepost: End Ahead Back: End Landmark: Main Message: Interstate 82 westbound at milepost 40 is closed due to icy conditions on the roadway and multiple collisions. WSDOT has treated the roadway and WSP is removing vehicles that are blocking the roadway due to being involved in collisions. (Tom)			

File: 800.12.11.8.12

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P08]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [7409]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
10/31/12		No changes			
10/4/12		LOW IMPACT I-82 Both Directions - I-82 near Grandview: Thursday, Oct. 4 from 7 a.m. to 12 p.m. noon between milepost 71 and milepost 73 both directions, expect single lane closures while WSP conducts an investigation. Last Updated: 9/29/2012 9:38 AM From milepost 71 to milepost 73 (Tom)			

File: 800.12.11.8.12

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P08]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [7409]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
8/31/12		No changes			
8/27/12		LOW IMPACT I-82 Eastbound - I-82 westbound: On Monday, August 27, there will be intermittent lane closures as crews install new guardrail. Traffic will be reduced to one lane through the construction zone from milepost 32 to milepost 58. Minor delays can be anticipated. Last Updated: 8/26/2012 1:29 AM From milepost 38 to milepost 58)Tom)			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P08]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [7409]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
5/1/12		SITE VISIT -- NGHIA -- Worked with crew to re-cut sensor # 2 and # 6. Those sensors still being disable in the system, Hoang will stop by and balance them this week.	Nghia		
5/8/12	7:30-9:30	SITE VISIT -- HOANG -- (7:30-9:30) Balanced sensors #1, #2, #5 and #6. Copied log and parameter files.	Hoang		
5/30/12		PROCESSED MANUAL COUNT: EB = 0.64%; WB = 0.87%; BWs = 0.61% -- OK -- BJ/RT			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P08]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [7409]</p>
---	--

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
3/31/12		NO CHANGES			
3/11/12		SR 97 closed mp 56 to mp 59 due to large dust storm; 20 collisions, traffic diverted SR 22 and 221			
3/13/12		HIGH IMPACT US 97 Both Directions - US 97 south of Toppenish near milepost 59, is closed due to blowing dust and poor visibility. WSDOT is setting up a detour via local roads. Last Updated: 3/13/2012 4:04 PM At milepost 59			
3/15/12		HIGH IMPACT US 97 Both Directions - Due to blowing dust and debris, WSDOT crews are piloting vehicles on US 97 from Rocky Ford Road, near milepost 59, to Pumphouse Road, near milpost 56 in both directions. Last Updated: 3/15/2012 1:35 PM From milepost 56 to milepost 59			
3/21/12	(08:45 – 09:15)	3/21/12 Buena-P08 (08:45 – 09:15) Site inspected. Copied log and parameter files. Sensors #2 and #6 are disabled in the system. Copies of site inspection are in G:\WIM\TEMP\HOANG\site inspectio2012 folder. (HN)	HN		